

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/10/2019

Submitted Date:

09/11/2019

Document Number:

696101280

FIELD INSPECTION FORM

Loc ID 317532 Inspector Name: Evins, Bret On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 7800
Name of Operator: BEREN CORPORATION
Address: 2020 N BRAMBLEWOOD STREET
City: WICHITA State: KS Zip: 67206

Findings:

20 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Reynolds, Rodney	(316) 337-8340	reynoldsr@berexco.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
100573	PIT	AC	09/23/1999		-	MOYER "A"	AC
100574	PIT	AC	09/23/1999		-	MOYER "A"	AC
100575	PIT	AC	09/23/1999		-	MOYER "A" 1	AC
239238	WELL	PR	07/29/2014	OW	123-07025	MOYER UNIT 14-29	PR
433344	TANK BATTERY	AC	04/14/2009		-	MOYER 'A'-612N56W 29SESW	AC

General Comment:

This is a WELL & BATTERY inspection.
Well is Producing | PR.
Battery: Active | In Operation
Centralized Battery serves 11 Location IDs (317535, 405727, 317531, 317533, 317536; 317530, 317532, 317529, 317526, 317525, 317534).
(5: wells, Active Injection | IJ ; 6: wells, Producing | PR).

Location

Lease Road:			
Type	Access		
comment:	Adequate		
Corrective Action:		Date:	

Overall Good:

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	<input style="width: 95%;" type="text"/>		
Corrective Action:	<input style="width: 95%;" type="text"/>	Date:	<input style="width: 80%;" type="text"/>

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Iron mesh panel		
Corrective Action:		Date:	
Type	PUMP JACK		
Comment:	Iron mesh panel		
Corrective Action:		Date:	
Type	PIT		
Comment:	Iron mesh panel		
Corrective Action:		Date:	
Type	TANK BATTERY		

Comment: Iron mesh panel		
Corrective Action:		Date:

Equipment:		corrective date
Type: Ancillary equipment	# 9	
Comment: At well: 1: Chemical pump, drum w/ drip containment 1: Drum to bleed fluid At Batt: 7: Chemical pumps w/ drums, tanks & drip containment.		
Corrective Action:		Date:
Type: FWKO	# 1	
Comment: 140 Bbls. capacity		
Corrective Action:		Date:
Type: Prime Mover	# 1	
Comment: Electric motor		
Corrective Action:		Date:
Type: Deadman # & Marked	# 4	
Comment: 4/4: Marked		
Corrective Action:		Date:
Type: Pump Jack	# 1	
Comment:		
Corrective Action:		Date:
Type: Bradenhead	# 1	
Comment: Appears plumbed to surface.		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		
Comment: Centralized Battery serves 11 Location IDs (317535, 405727, 317531, 317533, 317536; 317530, 317532, 317529, 317526, 317525, 317534). Refer also to Tank Battery Facility ID #433344.					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	200 BBLs	FIBERGLASS AST		
Comment:					
Corrective Action:					Date:
<u>Paint</u>					
Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					
<u>Berms</u>					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment: Shares berms w/ 300 Bbls. produced H2O tanks & FWKO.					
Corrective Action:					Date:
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	5	300 BBLs	STEEL AST		40.980338,-103.661201
Comment:					
Corrective Action:					Date:
<u>Paint</u>					
Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					
<u>Berms</u>					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	6	300 BBLs	FIBERGLASS AST		40.980504,-103.661013
Comment:					
Corrective Action:					Date:
<u>Paint</u>					
Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					
<u>Berms</u>					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	

Comment:	Shares berms w/ 200 Bbls. produced H2O tank & FWKO.	
Corrective Action:		Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 100573 Type: PIT API Number: - Status: AC Insp. Status: AC

Facility ID: 100574 Type: PIT API Number: - Status: AC Insp. Status: AC

Facility ID: 100575 Type: PIT API Number: - Status: AC Insp. Status: AC

Facility ID: 239238 Type: WELL API Number: 123-07025 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing | PR.](#)

Corrective Action:

Date:

Facility ID: 433344 Type: TANK API Number: - Status: AC Insp. Status: AC

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Type: Emergency Lined: NO Pit ID: 100573 Lat: 40.980121 Long: -103.661084

Reference Point: SE Other: _____ Length: _____ Width: _____

Lining:

Liner Type: _____ Liner Condition: _____

Comment:

Corrective

Date: _____

Fencing:

Fencing Type: Panel Fencing Condition: Adequate

Comment:

Corrective

Date: _____

Netting:

Netting Type: _____ Netting Condition: _____

Comment:

Corrective

Date: _____

Anchor Trench Present: _____ Oil Accumulation: NO 2+ feet Freeboard: YES

Comment: Multiple produced water pits. Foreman indicated only used for emergencies.

Corrective

Date: _____

Type: Emergency Lined: NO Pit ID: 100574 Lat: 40.979862 Long: -103.660615

Reference Point: SE Other: _____ Length: _____ Width: _____

Lining:

Liner Type: _____ Liner Condition: _____

Comment:

Corrective

Date: _____

Fencing:

Fencing Type: Panel Fencing Condition: Adequate

Comment:

Corrective

Date: _____

Netting:

Netting Type: _____ Netting Condition: _____

Comment:

Corrective

Date: _____

Anchor Trench Present:	Oil Accumulation: <u>NO</u>	2+ feet Freeboard: <u>YES</u>
Comment:	Multiple produced water pits. Foreman indicated only used for emergencies.	
Corrective		Date:
Type: <u>Emergency</u>	Lined: <u>NO</u>	Pit ID: <u>100575</u>
	Lat: <u>40.980183</u>	Long: <u>-103.660670</u>
Reference Point: <u>SE</u>	Other: _____	Length: _____
Width: _____		
Lining:		
Liner Type:	Liner Condition:	
Comment:		
Corrective		Date:
Fencing:		
Fencing Type: <u>Panel</u>	Fencing Condition: <u>Adequate</u>	
Comment:		
Corrective		Date:
Netting:		
Netting Type:	Netting Condition:	
Comment:		
Corrective		Date:
Anchor Trench Present:	Oil Accumulation: <u>NO</u>	2+ feet Freeboard: <u>YES</u>
Comment:	Multiple produced water pits. Foreman indicated only used for emergencies.	
Corrective		Date:

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary:</p> <p>On TUE 09/10/2019 at approximately 10:50 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: BEREN CORPORATION Location Name: MOYER 'A'-612N56W /29SESW Location ID: 317532 Well Name: Moyer Unit 14-29 API: 05-123-07025 Location County: Weld County, Colorado Weather: Damp w/ muddy & wet areas from prior rain.</p> <p>While there, I observed: Well(s) - 1: Producing PR. Battery: Active In Operation Centralized Battery serves 11 Location IDs (317535, 405727, 317531, 317533, 317536; 317530, 317532, 317529, 317526, 317525, 317534). (5: wells, Active Injection IJ ; 6: wells, Producing PR).</p> <p>NO: Corrective Actions observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	09/11/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696101281	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4934792

