

Inspection Photos

Location Name: MOYER 'A'-612N56W /29NESW

Location #: 317535



Photo #1

Moyer Unit 11-29 (05-123-07033) UIC - Wellsite

**Active Injection | IJ
Injecting**



Photo #2

Moyer Unit 11-29 UIC – Wellhead

**Active Injection | IJ
Injecting**

Inspection Photos

Location Name: MOYER 'A'-612N56W /29NESW

Location #: 317535



Colorado Oil & Gas Conservation Commission
40.98059, -103.66104, 1506.0m, 277°
09/10/2019 11:07:46 AM



Colorado Oil & Gas Conservation Commission
40.98053, -103.6612, 1522.0m, 347°
09/10/2019 01:45:18 PM

Photo #3

Moyer Unit UIC - Injection Facility

Moyer Unit 11-29, 13-29, 15-29, 3-32, 11-32 (UIC wells)

Photo #4

Moyer Unit UIC - Injection Facility

Injection pump
Injecting

Inspection Photos

Location Name: MOYER 'A'-612N56W /29NESW

Location #: 317535



Photo #5

Moyer Unit UIC - Injection Facility

Water Tanks



Photo #6

Moyer Unit UIC - Injection Facility

Crude Oil tanks