

Inspection Photos

Location Name: WIDOW WOMAN FEDERAL 42-7

API#: 05-071-07788

INSP. #: 6951013



Colorado Oil & Gas Conservation Commission
37.10199, -104.70587, 2084.0m, 287°
2019/09/10 11:49:31

PHOTO 1: WELLHEAD



Colorado Oil & Gas Conservation Commission
37.17414, -104.50151, 94°
2019/09/10 11:48:56

PHOTO 2: WELL SIGN

Inspection Photos

Location Name: WIDOW WOMAN FEDERAL 42-7

API#: 05-071-07788

INSP. #: 6951013



PHOTO 3: CULVERT ON ROW NORTH OF LOCATION IS PLUGGED. CLEAN CULVERT AND PROPERLY MAINTAIN BMP'S, COMPLY WITH RULE 1002.f. CA DATE 11-10-19



PHOTO 4: EROSION IN BMP DITCH NORTH OF LOCATION. REPAIR EROSION IN DITCH, ADD ADDITIONAL BMP'S TO SLOW STORM WATER FLOW AND PREVENT FURTHER EROSION. COMPLY WITH RULE 1002.f. CA DATE 11-10-19

Inspection Photos

Location Name: WIDOW WOMAN FEDERAL 42-7

API#: 05-071-07788

INSP. #: 6951013



PHOTO 5: EROSION IN BMP DITCH NORTH OF LOCATION. SEDIMENT FROM UP GRADE OF DITCH HAS FILLED DITCH CAUSING EROSION TO EXTEND INTO DRIVING PATH ON ROW. REPAIR EROSION IN DITCH, ADD ADDITIONAL BMP'S TO SLOW STORM WATER FLOW AND PREVENT FURTHER EROSION. COMPLY WITH RULE 1002.f. CA DATE 11-10-19



PHOTO 6: CULVERT ON DOWN GRADE SIDE OF ROW APPEARS TO BE TOO SHORT CAUSING FILL FROM ROW TO ERODE. REPAIR EROSION, INSTALL PROPER BMP'S TO PREVENT EROSION AND SEDIMENT FROM ROW TO MIGRATE PAST THE ORIGINAL ROW DISTURBANCE AREA, COMPLY WITH RULE 1002.f. CA DATE 11-10-19.

Inspection Photos

Location Name: WIDOW WOMAN FEDERAL 42-7

API#: 05-071-07788

INSP. #: 6951013



**PHOTO 7: EROSION IN BMP DITCH NORTH OF LOCATION.
REPAIR EROSION IN DITCH, ADD ADDITIONAL BMP'S TO
SLOW STORM WATER FLOW AND PREVENT FURTHER
EROSION. COMPLY WITH RULE 1002.f. CA DATE 11-10-19**



**PHOTO 8: EROSION IN BMP DITCH NORTH OF LOCATION.
REPAIR EROSION IN DITCH, ADD ADDITIONAL BMP'S TO
SLOW STORM WATER FLOW AND PREVENT FURTHER
EROSION. COMPLY WITH RULE 1002.f. CA DATE 11-10-19**

Inspection Photos

Location Name: WIDOW WOMAN FEDERAL 42-7

API#: 05-071-07788

INSP. #: 6951013



**PHOTO 9: EROSION IN BMP DITCH NORTH OF LOCATION.
REPAIR EROSION IN DITCH, ADD ADDITIONAL BMP'S TO
SLOW STORM WATER FLOW AND PREVENT FURTHER
EROSION. COMPLY WITH RULE 1002.f. CA DATE 11-10-19**



**PHOTO 8: EROSION IN BMP DITCH NORTH OF LOCATION.
REPAIR EROSION IN DITCH, ADD ADDITIONAL BMP'S TO
SLOW STORM WATER FLOW AND PREVENT FURTHER
EROSION. COMPLY WITH RULE 1002.f. CA DATE 11-10-19**

Inspection Photos

Location Name: WIDOW WOMAN FEDERAL 42-7

API#: 05-071-07788

INSP. #: 6951013



PHOTO 11: VEGETATION IN BM' DITCH IS CAUSING STORWATER TO BYPASS THE CULVERT THAT IS RIGHT BEHIND THE VEGETATION IN PHOTO AND ERODE ROW DRIVE PATH. REMOVE VETETATION AND REPAIR EROSION IN DITCH, ADD ADDITIONAL BMP'S TO SLOW STORM WATER FLOW AND PREVENT FURTHER EROSION. COMPLY WITH RULE 1002.f. CA DATE 11-10-19