

FRAM OPERATING LLC – 10310

Location ID # 334481

API # 05-077-09325 Seminole 32-2-I

API # 05-077-09326 Seminole 32-2-L

API # 05-077-09327 Seminole 32-2-J

Inspection Date : 9/9/2019



**GoogleEarth view of location area showing access road with entrance gate to location off Forest Service Rd 70 (FS.70).
Image date 6/17/2016.**



**GoogleEarth view of location area.
Image date 6/17/2016.**

FRAM OPERATING LLC – 10310

Location ID # 334481

API # 05-077-09325 Seminoe 32-2-I

API # 05-077-09326 Seminoe 32-2-L

API # 05-077-09327 Seminoe 32-2-J

Inspection Date : 9/9/2019



Entrance gate to location off Forest Service Rd 70 (FS.70).

Lock removed, gate open.

Mesa County Land Development Application sign on fence.



Overview of location from N entrance of pad looking S

FRAM OPERATING LLC – 10310

Location ID # 334481

API # 05-077-09325 Seminoe 32-2-I

API # 05-077-09326 Seminoe 32-2-L

API # 05-077-09327 Seminoe 32-2-J

Inspection Date : 9/9/2019



NE corner of location looking SW



SE corner of location looking NW

FRAM OPERATING LLC – 10310

Location ID # 334481

API # 05-077-09325 Seminoe 32-2-I

API # 05-077-09326 Seminoe 32-2-L

API # 05-077-09327 Seminoe 32-2-J

Inspection Date : 9/9/2019



SW corner of location looking N



SW corner of location looking NE

FRAM OPERATING LLC – 10310

Location ID # 334481

API # 05-077-09325 Seminoe 32-2-I

API # 05-077-09326 Seminoe 32-2-L

API # 05-077-09327 Seminoe 32-2-J

Inspection Date : 9/9/2019



05-077-09325 Seminoe 32-2-I

**Wellhead with sign and pump jack. Well Temporarily abandoned.
Stained soil around wellhead.**

05-077-09326 Seminoe 32-2-L

Wellhead with sign and pump jack. Stained soil around wellhead.

FRAM OPERATING LLC – 10310

Location ID # 334481

API # 05-077-09325 Seminole 32-2-I

API # 05-077-09326 Seminole 32-2-L

API # 05-077-09327 Seminole 32-2-J

Inspection Date : 9/9/2019



05-077-09327 Seminole 32-2-J. Wellhead with sign.
2" hose connected to wellhead flowing to meter. (A)
2" hose from meter to production riser at wellhead. (B)



Meter housing with sides open. Looking S.
2" hose connected to wellhead flowing to meter. (A)
2" hose from meter to production riser at wellhead. (B)
Parts, pipe and fittings scattered around .

FRAM OPERATING LLC – 10310

Location ID # 334481

API # 05-077-09325 Seminoe 32-2-I

API # 05-077-09326 Seminoe 32-2-L

API # 05-077-09327 Seminoe 32-2-J

Inspection Date : 9/9/2019



Separator with metal berm. SE corner looking NW.
Unused pipe fencing



Separator with metal berm. NE corner looking SW

FRAM OPERATING LLC – 10310

Location ID # 334481

API # 05-077-09325 Seminoe 32-2-I

API # 05-077-09326 Seminoe 32-2-L

API # 05-077-09327 Seminoe 32-2-J

Inspection Date : 9/9/2019



Tank Battery NE corner looking SW



Tank Battery SW corner looking NE

FRAM OPERATING LLC – 10310

Location ID # 334481

API # 05-077-09325 Seminole 32-2-I

API # 05-077-09326 Seminole 32-2-L

API # 05-077-09327 Seminole 32-2-J

Inspection Date : 9/9/2019



**Flowline risers on NW Corner of separator berm.
4x-2" and 1x-1"**



**1" flowline riser.
Fuel gas supply for 05-077-09326 Seminole 32-2-L pump jack.**

FRAM OPERATING LLC – 10310

Location ID # 334481

API # 05-077-09325 Seminoe 32-2-I

API # 05-077-09326 Seminoe 32-2-L

API # 05-077-09327 Seminoe 32-2-J

Inspection Date : 9/9/2019



**Needs update on As-Drilled locations. Red dots are COGIS database coordinates.
Red arrows point to actual wellheads.**

FRAM OPERATING LLC – 10310

Location ID # 334481

API # 05-077-09325 Seminoe 32-2-I

API # 05-077-09326 Seminoe 32-2-L

API # 05-077-09327 Seminoe 32-2-J

Inspection Date : 9/9/2019



500 gal propane tank. Disconnected.



Cement barricades. Unused.

FRAM OPERATING LLC – 10310

Location ID # 334481

API # 05-077-09325 Seminole 32-2-I

API # 05-077-09326 Seminole 32-2-L

API # 05-077-09327 Seminole 32-2-J

Inspection Date : 9/9/2019



**Spill Response Kit . Contents scattered about by vandals.
05-077-09326 Seminole 32-2-L wellhead in background.**



Meter house and tool box. Scattered by vandals.

FRAM OPERATING LLC – 10310

Location ID # 334481

API # 05-077-09325 Seminoe 32-2-I

API # 05-077-09326 Seminoe 32-2-L

API # 05-077-09327 Seminoe 32-2-J

Inspection Date : 9/9/2019



05-077-09325 Seminoe 32-2-I. Looking N
Well Temporarily abandoned. Pump Jack disconnected. Pump Jack motor removed.
Vandalized spill response kit in background.



05-077-09325 Seminoe 32-2-I. Looking E
Well Temporarily abandoned. Pump Jack disconnected
Stained soil around wellhead. Vandalized spill response kit in background

FRAM OPERATING LLC – 10310

Location ID # 334481

API # 05-077-09325 Seminoe 32-2-I

API # 05-077-09326 Seminoe 32-2-L

API # 05-077-09327 Seminoe 32-2-J

Inspection Date : 9/9/2019



**Pump Jack with pipe fence. Looking N.
Located at 05-077-09326 Seminoe 32-2-L wellhead**



**Injection chemical tank and pump/containment unit vandalized.
Located at 05-077-09326 Seminoe 32-2-L wellhead**

FRAM OPERATING LLC – 10310

Location ID # 334481

API # 05-077-09325 Seminoe 32-2-I

API # 05-077-09326 Seminoe 32-2-L

API # 05-077-09327 Seminoe 32-2-J

Inspection Date : 9/9/2019



**Spill Response Kit materials at E end of tank battery, scattered/stolen by vandals.
Injection chemical tank stolen and pump/containment unit vandalized.
Oil contaminated buckets and tubs.**



**Spill Response Kit materials at E end of tank battery,
scattered/stolen by vandals.
Oil contaminated buckets and tubs.**

FRAM OPERATING LLC – 10310

Location ID # 334481

API # 05-077-09325 Seminoe 32-2-I

API # 05-077-09326 Seminoe 32-2-L

API # 05-077-09327 Seminoe 32-2-J

Inspection Date : 9/9/2019



**Injection chemical tank stolen and pump/containment unit vandalized.
Oil contaminated buckets and tubs.**



**2" Production riser to tank. Located on NE corner of tank battery.
Spill response materials scattered by vandal. Oil stained soil.**

FRAM OPERATING LLC – 10310

Location ID # 334481

API # 05-077-09325 Seminoe 32-2-I

API # 05-077-09326 Seminoe 32-2-L

API # 05-077-09327 Seminoe 32-2-J

Inspection Date : 9/9/2019



Lube oil tank for pump jack with no secondary containment.



2" Production riser to tank. Located on NW corner of tank battery.