

FRAM OPERATING LLC – 10310

Location ID # 334472

API # 05-077-08922 Jensen #1-3

API # 05-077-09311 Jensen #1-3-O

Inspection Date : 9/9/2019



GoogleEarth view of location area showing access road with entrance to residence and location off Kannah Creek Rd (GS.00). Image date 6/17/2016.



GoogleEarth view of location area.
Image date 6/17/2016.

FRAM OPERATING LLC – 10310

Location ID # 334472

API # 05-077-08922 Jensen #1-3

API # 05-077-09311 Jensen #1-3-O

Inspection Date : 9/9/2019



Location entrance from NE corner looking SW



Location overview from NE corner looking W

FRAM OPERATING LLC – 10310

Location ID # 334472

API # 05-077-08922 Jensen #1-3

API # 05-077-09311 Jensen #1-3-O

Inspection Date : 9/9/2019



Location entrance from SE corner looking W



Location overview from SE corner looking N

FRAM OPERATING LLC – 10310

Location ID # 334472

API # 05-077-08922 Jensen #1-3

API # 05-077-09311 Jensen #1-3-O

Inspection Date : 9/9/2019



Tank Battery. Looking N.



Flowline to tank batter on S side. Looking W.

FRAM OPERATING LLC – 10310

Location ID # 334472

API # 05-077-08922 Jensen #1-3

API # 05-077-09311 Jensen #1-3-O

Inspection Date : 9/9/2019



**4" gathering line riser. Locked out/tagged out.
Pipe barricade.**



Meter housing. Looking N.

FRAM OPERATING LLC – 10310

Location ID # 334472

API # 05-077-08922 Jensen #1-3

API # 05-077-09311 Jensen #1-3-O

Inspection Date : 9/9/2019



Separator with metal berms. NE corner of berm Looking SW.



Separator with metal berms. NW corner of berm Looking SE.