

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/11/2019

Submitted Date:

09/11/2019

Document Number:

699300145**FIELD INSPECTION FORM**
 Loc ID 336278 Inspector Name: Revas, Robbie On-Site Inspection ☐ 2A Doc Num:                     
**Operator Information:**OGCC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1675 BROADWAY, STE 2800City: DENVER State: CO Zip: 80202**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**14 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**
**Contact Information:**

Contact Name	Phone	Email	Comment
Gomez, Jason		jason.gomez@state.co.us	
,		cogcc@kpk.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
240099	WELL	PR	03/01/2012	OW	123-07887	GEORGE H. GERHARDT 1	PR
262117	WELL	TA	08/04/2016	GW	123-20704	KERR 5-24A	TA

**General Comment:**

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Adequate		
Corrective Action	L	Date:	

Overall Good: ☒

<b>Signs/Marker:</b>			
Type	OTHER		
Comment:	Kerr McGee TA well has had wH sign installed		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	No indication of wells it serves		
Corrective Action:	Install sign to comply with Rule 210.b.	Date:	11/27/2018

Emergency Contact Number:

Comment:		
Corrective Action:		Date: _____

Overall Good: ☒

<b>Spills:</b>				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				

<b>Fencing/:</b>			
Type	PUMP JACK		
Comment:	Fabricated steel pipe		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	AG fencing KerrMcGee WH		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	

Type: Prime Mover	# 1		
Comment:	electric motor		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 2		
Comment:	Appear to be plumbed to surface		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 2		
Comment:	Automation, Electrical transformers, breaker panel and meter.		
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	BV CONCRETE		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	
Other (Content)	
Other (Capacity)	50 bbl
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	

Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type			
Comment:			
Corrective Action:			Date:

**Inspected Facilities**Facility ID: 240099 Type: WELL API Number: 123-07887 Status: PR Insp. Status: PR**Producing Well**Comment: PR Shares loc. with TA Kerr McGee well.

Corrective Action:

Date:

Facility ID: 262117 Type: WELL API Number: 123-20704 Status: TA Insp. Status: TA**Idle Well**Purpose: ☐ Shut In☒ Temporarily Abandoned

Reminder: \_\_\_\_\_

Comment: TA

Corrective Action:

Date: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
<p><b>COGCC Inspection Report Summary</b></p> <p>On Wednesday 9/11/19 at approximately 1500 hrs. I, Inspector Robbie Revas, Conducted an on-site Follow up inspection at the George H Gerhardt #1 KP Kauffman, API #05-123-07887 per Doc. # 685100735 and # 691401100 in Weld County Colorado.</p> <p>While there, I observed Producing Well and TB well. Well report shows it to be PR at the time of this inspection it appears to be PR. Location is shared with a TA Kerr McGee well.</p> <p>During this inspection the following compliance issues were observed to have been addressed: 210.b well that shares location doesn't have a sign, has a sign installed. See photo #3.</p> <p>605.d stained soil and possible leak around what appears to be a flow line manifold has been addressed. See photo # 12</p> <p>603.f stained soil around WH has been addressed see photo #2</p> <p>603.f Unused , unmarked risers has been addressed see photos #7, 8, 9, 10 and 11.</p> <p>CA for 210.b Tank battery sign indicating what wells it serves is still delinquent as of 11/27/2018 per Doc. # 691401100. Install sign to comply with rule 210.b</p> <p>Location is dry, weather is cloudy.</p> <p>A follow up on this site inspection needs to be conducted to ensure that the compliance issue is addressed to comply with COGCC rules.</p> <p>Continuing education COGCC Inspection Report Summary.</p>	revasr	09/11/2019

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699300146	Loc. pics	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4935036">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4935036</a>