

FRAM OPERATING LLC – 10310

Location ID # 312710

API # 05-077-08872 Doty #1-1

Inspection Date : 9/9/2019



GoogleEarth view of location area showing access road with entrance off Divide Rd. Image date 6/17/2016.



**GoogleEarth view of location area.
Image date 6/17/2016.**

FRAM OPERATING LLC – 10310

Location ID # 312710

API # 05-077-08872 Doty #1-1

Inspection Date : 9/9/2019



Location overview from SW entrance looking NE.

Weeds



Location overview from SW corner looking NE.

Weeds

FRAM OPERATING LLC – 10310

Location ID # 312710

API # 05-077-08872 Doty #1-1

Inspection Date : 9/9/2019



Meter housing and Separator looking NE
Weeds. 2" flowline riser w/ plug.



Wellhead. Locked out / tagged out.
Weeds

FRAM OPERATING LLC – 10310

Location ID # 312710

API # 05-077-08872 Doty #1-1

Inspection Date : 9/9/2019



**Tank with earth berms looking N.
Weeds**



**2"x 4" gather line riser w/ pipe barricade. LO/TO. Looking SW
Weeds**

FRAM OPERATING LLC – 10310

Location ID # 312710

API # 05-077-08872 Doty #1-1

Inspection Date : 9/9/2019



Equipment overview looking W



Equipment overview looking E