

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/05/2019

Submitted Date:

09/05/2019

Document Number:

679705327**FIELD INSPECTION FORM**
 Loc ID 314690 Inspector Name: Moran, Rick On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 10027Name of Operator: C & J FIELD SERVICESAddress: 3650 COUNTY RD #2City: RANGELY State: CO Zip: 81648**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**7 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Kellerby, Shaun	970-712-1248	shaun.kellerby@state.co.us	
,	970-629-5161	candjfield@centurytel.net	All inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
229274	WELL	PR	10/01/2017	OW	103-06369	HARRISON-SMITH 2	PR

General Comment:[COGCC Inspection Report Summary.](#)[On 9-5-2019 at approximately 9:00, inspector Rick Moran, conducted a routine inspection at C & J Field Servies well Lebauer 2 in Rio Blanco county.](#)[During this inspection the following compliance issues were observed:](#)[1\) Stained soil at well head. Photo 2. Complete by 10-5-2019.](#)[A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.](#)[Note: Well venting casing gas. A 3 cubic foot bag filled with gas in 35 minutes. Photos 2, 3 & 4.](#)[This is a summary of inspection report 679705327.](#)

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911 label at tank battery located nearest well Harrison Smith 4 (05-103-07932).

Corrective Action:

Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	Stained soil at well head.		
Corrective Action:	Properly treat or dispose of oily waste in accordance with 907.e.	Date:	10/05/2019

Overall Good: ☐

Spills:					
Type	Area	Volume			

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

Type: Deadman # & Marked	# 6		corrective date
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No	YES		
Comment:	Well venting casing gas. A 3 cubic foot bag filled with gas in 35 minutes.		
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	229274	Type:	WELL	API Number:	103-06369	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Pump jack idle at time of inspection.								
Corrective Action:				Date:					

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [No apparent significant soil migration, erosion, or soil movement on location.](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402167950	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4929961
679705328	inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4929913