

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/12/2019

Submitted Date:

09/12/2019

Document Number:

693501393**FIELD INSPECTION FORM**

Loc ID 320135 Inspector Name: Silver, Randy On-Site Inspection ☐ 2A Doc Num:

Operator Information:OGCC Operator Number: 10602Name of Operator: MCCLANE ENERGY INCAddress: 1412 103 RD AVECity: NORTHGLENN State: CO Zip: 80260**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
☒ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:16 Number of Comments10 Number of Corrective Actions☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Pesicka, Conor		conor.pesicka@state.co.us	
MCCLANE, GENE		genemcclane@hotmail.com	All inspections
Hickey, Mike		michael.hickey@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
202786	WELL	PR	08/01/2016	OW	001-08191	VAN SCOYK 1	SI

General Comment:

Location

Overall Good: ☒

Signs/Marker:			
Type	BATTERY		
Comment:	Emergency contact number is not a working number Sign not posted or information inaccurate at well(s) or battery		
Corrective Action:	Install sign to comply with Rule 210.b.	Date:	10/12/2019
Type	WELLHEAD		
Comment:	Emergency contact number is not a working number		
Corrective Action:	Sign not posted or information inaccurate at well(s) or battery	Date:	10/12/2019
Type	TANK LABELS/PLACARDS		
Comment:	NEPA label on produced water tank has flammability number of 0 10/20/2016 FIR Doc#678800128 indicates that this label should have a minimum flammability of 1		
Corrective Action:	Install sign to comply with Rule 210.d.	Date:	11/22/2016

Emergency Contact Number:

Comment:	Emergency contact number at Battery and WH are not working numbers.		
Corrective Action:	Install sign to comply with Rule 210.b.	Date:	10/12/2019

Good Housekeeping:

Type	WEEDS		
Comment:	WEEDS in and around TNK BTRY, separator, PU and WH		
Corrective Action:	Comply with rule 603f	Date:	10/12/2019
Type	UNUSED EQUIPMENT		
Comment:	PU motor		
Corrective Action:	Comply with rule 603 f	Date:	11/05/2018
Type	OTHER		
Comment:	Stained soil around WH		
Corrective Action:	Properly treat or dispose of oily waste in accordance with 907.e.	Date:	11/05/2018
Type	OTHER		
Comment:	Stained soil around PU base and motor		
Corrective Action:	Non E&P Waste not properly stored, handled, transported, treated, or disposed per Rule 907A	Date:	11/05/2018
Type	TRASH		
Comment:	Cans, buckets, bricks		
Corrective Action:	Comply with rule 603 f	Date:	10/19/2018
Type	OTHER		
Comment:	Mechanical issues: WH and PU		
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.	Date:	11/05/2018

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type			
Comment:			
Corrective Action:		Date:	

Equipment:			corrective date
Type: Bradenhead	# 1		
Comment:	Appears to be plumbed to surface		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Gas powered motor		
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				

Corrective Action:					Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	OTHER	Open Top		,	
Comment:						
Corrective Action:					Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	80bbl	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment: Shares containment with crude oil tank				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities

Facility ID: 202786 Type: WELL API Number: 001-08191 Status: PR Insp. Status: SI

Idle Well

Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: EQUIPMENT ONSITE

Comment: SI

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Thursday September 12, 2019 at approximately 1:51PM, I, Inspector Randy Silver, conducted an on-site inspection at a MCCLANE energy INC site Van Scoyk #1, at API# 05-001-08191 in Adams County Colorado.</p> <p>While there, I observed well site and TNK BTRY</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Sign: Rule 210 b Corrective action date of 10-12-19 See photo1</p> <p>Stained soil: Rule 907 e Corrective action date of 11-5-18 See photos 2,3</p> <p>Placards: Rule 210 d Corrective action date of 11-22-16 See photo 8</p> <p>Mechanical issue: Rule 605 d Corrective action date of 10-19-18 See photos 3,4,5</p> <p>Weeds: Rule 603 f Corrective action date of 10-12-19 See photos 2,6,7,8,9</p> <p>Stained soil: Rule 907 A Corrective action date of 11-5-18 See photos 4,5</p> <p>Trash: Rule 603 f Corrective action date of 10-19-18 See photo 6</p> <p>Unused equipment: Rule 603 f Corrective action date of 11-5-18 See photo6</p> <p>Weather conditions: Clear and location dry</p> <p>I tried to call emergency contact number but not a working number looked in operator file called emergency number listed and as soon as said who I was they hung up. Called other number listed and spoke with a women who stated the operator was not working the well anymore and was going to let it go.</p> <p>This is a follow up inspection per Doc#691401135 at time of inspection all corrective actions had not been addressed. Well site and TNK BTRY locations appears to not have been maintained in quit some time.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	silverr	09/12/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693501394	loc pic	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4935952