

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/12/2019

Submitted Date:

09/12/2019

Document Number:

699500056

FIELD INSPECTION FORM

Loc ID 433741 Inspector Name: MEDINA, JUSTIN On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10330
Name of Operator: INVESTMENT EQUIPMENT LLC
Address: 412 W PLATTE AVE
City: FT MORGAN State: CO Zip: 80701

Findings:

- 4 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

| Contact Name | Phone | Email | Comment |
|---------------------|----------------|-------------------------------|------------------|
| Koehler, Bob | | bob.koehler@state.co.us | |
| Chisholm, James Jr. | | investmentequipment@gmail.com | |
| FLOURNOY, BOB | 214-978-2500 | bobflournoy@att.net | PRESIDENT |
| Highberger, Kathryn | (970) 867-9007 | dkama@kci.net | Designated Agent |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|--------------------|-------------|
| 433744 | WELL | WO | 05/23/2014 | SI | 001-09770 | Badger Creek 22-41 | TA |

General Comment:

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

| Type | Area | Volume | | |
|------|------|--------|--|--|
| | | | | |

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

| | | | |
|--------------------|----|-------|--|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

Inspected Facilities

Facility ID: 433744 Type: WELL API Number: 001-09770 Status: WO Insp. Status: TA

Underground Injection Control

UIC Violation: Other Maximum Injection Pressure: _____

UIC Routine

| | | | |
|------------|---|------------------------------|-----------------------------|
| Inj./Tube: | Pressure or inches of Hg _____ (e.g. 30 psig or -30" Hg) | Previous Test Pressure _____ | MPP _____ |
| TC: | Pressure or inches of Hg _____ | Previous Test Pressure _____ | Inj Zone: <u>DSND</u> |
| Brhd: | Pressure or inches of Hg _____ | Previous Test Pressure _____ | Last MIT: <u>07/14/2015</u> |
| | | | AnnMTReq: _____ |

Comment: Well has been TA since July of 2015. MIT was performed. MIT will be due next July

Corrective Action: Date: _____

Method of Injection: _____

Test Type: _____ Tbg psi: _____ Csg psi: _____ BH psi: _____

Insp. Status: _____

Comment:

Corrective Action: Date: _____

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| | | | | | | |

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

| Comment | User | Date |
|--|---------|------------|
| At time of inspection location appears to be in compliance with COGCC rules. | medinaj | 09/12/2019 |

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------|---|
| 699500057 | pics | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4936216 |