

FRAM OPERATING LLC – 10310

Location ID # 334484

API # 05-077-08886 Eberly #23-4

API # 05-077-09314 Eberly #23-4-M

Inspection Date : 9/9/2019



GoogleEarth view of location area showing access road with entrance off Reeder Mesa Rd. Image date 6/17/2016.



GoogleEarth view of location.
Image date 6/17/2016

FRAM OPERATING LLC – 10310

Location ID # 334484

API # 05-077-08886 Eberly #23-4

API # 05-077-09314 Eberly #23-4-M

Inspection Date : 9/9/2019



Gate at location entrance. Looking E.



**Location overview from SE corner looking NW.
Weeds.**

FRAM OPERATING LLC – 10310

Location ID # 334484

API # 05-077-08886 Eberly #23-4

API # 05-077-09314 Eberly #23-4-M

Inspection Date : 9/9/2019



View from NW corner looking E.



View from SW corner looking NE

FRAM OPERATING LLC – 10310

Location ID # 334484

API # 05-077-08886 Eberly #23-4

API # 05-077-09314 Eberly #23-4-M

Inspection Date : 9/9/2019



**Large pile of road base material along E edge of location.
View from SE corner looking N.
Weeds**



**Fencing around wellheads looking N.
Weeds.**

FRAM OPERATING LLC – 10310

Location ID # 334484

API # 05-077-08886 Eberly #23-4

API # 05-077-09314 Eberly #23-4-M

Inspection Date : 9/9/2019



**API #05-077-08886 Wellhead with sign.
Temporarily abandoned.
Overgrown with weeds.**



API #05-077-08886 Wellhead

FRAM OPERATING LLC – 10310

Location ID # 334484

API # 05-077-08886 Eberly #23-4

API # 05-077-09314 Eberly #23-4-M

Inspection Date : 9/9/2019



**API #05-077-09314 Wellhead.
Overgrown with weeds.**



API #05-077-09314 Wellhead. Temporarily abandoned.