

**FRAM OPERATING LLC – 10310**

**Location ID # 311749**

**API # 05-077-09459 Kelly #23-2-B**

**Inspection Date : 9/9/2019**



**GoogleEarth view of location area showing access road with entrance off Reeder Mesa Rd. Image date 6/17/2016.**



**GoogleEarth view of location.  
Image date 6/17/2016**



**FRAM OPERATING LLC – 10310**

**Location ID # 311749**

**API # 05-077-09459 Kelly #23-2-B**

**Inspection Date : 9/9/2019**



**Gate at location entrance. Looking E.**



**Access road from SW corner of location looking W at entrance gate.  
Weeds.**



**FRAM OPERATING LLC – 10310**

**Location ID # 311749**

**API # 05-077-09459 Kelly #23-2-B**

**Inspection Date : 9/9/2019**



**Location overview from NW corner looking SE.  
Weeds.**



**Location overview from SW corner looking E.  
Weeds.**



**FRAM OPERATING LLC – 10310**

**Location ID # 311749**

**API # 05-077-09459 Kelly #23-2-B**

**Inspection Date : 9/9/2019**



**Location overview from SE corner looking NW.  
Large pile of road base material along E edge of location.  
Weeds.**



**Location overview from NE corner looking SW.  
Large pile of road base material along E edge of location  
Weeds.**



**FRAM OPERATING LLC – 10310**

**Location ID # 311749**

**API # 05-077-09459 Kelly #23-2-B**

**Inspection Date : 9/9/2019**



**API # 05-077-09459 Kelly #23-2-B**  
**Wellhead with sign and pipe barricade looking SE**  
**Temporarily abandoned. Weeds,**



**API # 05-077-09459 Kelly #23-2-B**  
**Wellhead with sign and pipe barricade looking N.**  
**Rat hole with cover next to T-post in foreground.**



**FRAM OPERATING LLC – 10310**

**Location ID # 311749**

**API # 05-077-09459 Kelly #23-2-B**

**Inspection Date : 9/9/2019**



**API # 05-077-09459 Kelly #23-2-B**

**Wellhead with bradenhead valve to surface.**



**API # 05-077-09459 Kelly #23-2-B**

**Wellhead showing area of audible gas leak at  
Surface Casing and Production Casing seal.**



**FRAM OPERATING LLC – 10310**

**Location ID # 311749**

**API # 05-077-09459 Kelly #23-2-B**

**Inspection Date : 9/9/2019**



**South Gate on access road looking NE.  
Gathering Line risers in background**



**Gathering Line risers. 4", 6" & 8"  
Locked out/ tagged out with blind flange.**