

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/12/2019

Submitted Date:

09/12/2019

Document Number:

699300157

FIELD INSPECTION FORM

Loc ID 332868 Inspector Name: Revas, Robbie On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 47120
Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP
Address: P O BOX 173779
City: DENVER State: CO Zip: 80217-

Findings:

- 12 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

| Contact Name | Phone | Email | Comment |
|--------------|-------|-------------------------------|---------------------------------|
| , | | COGCCinspections@anadarko.com | All Inspections |
| Gomez, Jason | | jason.gomez@state.co.us | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-------------------------|-------------|
| 241932 | WELL | TA | 06/01/2019 | GW | 123-09723 | MCCOY,PHILLIP UNIT E 1A | TA |

General Comment:

| Location | | | |
|--|---|--------|-----------------|
| Lease Road: | | | |
| Type | Access | | |
| comment: | Appears weeds have overgrown access road | | |
| Corrective Action: | Comply with Rule 603.f 10 days for weeds. | Date: | 10/30/2019 |
| Overall Good: <input type="checkbox"/> | | | |
| Signs/Marker: | | | |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | Adequate | | |
| Corrective Action: | | Date: | |
| Type | BATTERY | | |
| Comment: | Adequate | | |
| Corrective Action: | | Date: | |
| Type | WELLHEAD | | |
| Comment: | Adequate | | |
| Corrective Action: | | Date: | |
| Emergency Contact Number: | | | |
| Comment: | | | |
| Corrective Action: | | | Date: _____ |
| Good Housekeeping: | | | |
| Type | UNUSED EQUIPMENT | | |
| Comment: | Unused Fabricated steel pipe fence and Disconnected electric panel | | |
| Corrective Action: | Comply with Rule 603.f 30 days for unused equipment when machinery is not required to remove the equipment. | Date: | 10/12/2019 |
| Overall Good: <input type="checkbox"/> | | | |
| Spills: | | | |
| Type | Area | Volume | |
| In Containment: No | | | |
| Comment: | | | |
| <input type="checkbox"/> Multiple Spills and Releases? | | | |
| Fencing/: | | | |
| Type | WELLHEAD | | |
| Comment: | AG fence | | |
| Corrective Action: | | Date: | |
| Type | TANK BATTERY | | |
| Comment: | Fabricated steel fencing | | |
| Corrective Action: | | Date: | |
| Equipment: | | | |
| Type: Bird Protectors | # 7 | | corrective date |
| Comment: | | | |

| | | | |
|-----------------------------------|---------------------------------|-------|--|
| Corrective Action: | | Date: | |
| Type: Vertical Separator | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: FWKO | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Plunger Lift | # 2 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Emission Control Device | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Gas Meter Run | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Horizontal Heated Separator | # 6 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Bradenhead | # 2 | | |
| Comment: | Appear to be plumbed to surface | | |
| Corrective Action: | | Date: | |
| Type: Dehydrator | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Ancillary equipment | # 10 | | |
| Comment: | electric panels | | |
| Corrective Action: | | Date: | |
| Type: LACT | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---|----------|----------------|---------|--------|
| PRODUCED WATER | 1 | OTHER | FIBERGLASS AST | | , |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | |
|------------------|----------|
| Condition | Adequate |
| Other (Content) | |
| Other (Capacity) | 210 bbl |

| | | | | | | |
|--------------------|----------|---------------------|---------------------|-------------|--------|-------|
| Other (Type) | | | | | | |
| Berms | | | | | | |
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | | |
| Metal | Adequate | Walls Sufficent | Base Sufficent | Adequate | | |
| Comment: | | | | | | |
| Corrective Action: | | | | | | Date: |
| Contents | # | Capacity | Type | Tank ID | SE GPS | |
| CRUDE OIL | 1 | 300 BBLs | STEEL AST | | , | |
| Comment: | | | | | | |
| Corrective Action: | | | | | | Date: |
| Paint | | | | | | |
| Condition | Adequate | | | | | |
| Other (Content) | | | | | | |
| Other (Capacity) | | | | | | |
| Other (Type) | | | | | | |
| Berms | | | | | | |
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | | |
| Metal | Adequate | Walls Sufficent | Base Sufficent | Adequate | | |
| Comment: | | | | | | |
| Corrective Action: | | | | | | Date: |
| Venting: | | | | | | |
| Yes/No | NO | | | | | |
| Comment: | | | | | | |
| Corrective Action: | | | | | | Date: |
| Flaring: | | | | | | |
| Type | | | | | | |
| Comment: | | | | | | |
| Corrective Action: | | | | | | Date: |

Inspected Facilities

Facility ID: 241932 Type: WELL API Number: 123-09723 Status: TA Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action: Date: _____

COGCC Comments

| Comment | User | Date |
|--|--------|------------|
| <p>COGCC Inspection Report Summary On Thursday 9/12/2019 at approximately 1200 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at the McCoy, Phillip unit E #1A Kerr McGee, at API #05-123-09723 in Weld County Colorado.. While there, I observed Shut In Well and TB. Report shows it as SI since June 2019 and at the time of this inspection it appears to be SI and LO. Form 42 submitted on 8/9/17 Doc. #401369939 During this inspection the following compliance issues were observed: Housekeeping: Weeds growing all around Well site it appears that there is no visible access road. Comply with Rule 603.f, 10 days for weeds. CA date 9/22/2019 see photo #4 Housekeeping: Unused Equipment Fabricated steel pipe fence and disconnected electric panel. Comply with Rule 603.f, 30 days for unused equipment when machinery is not required to remove the equipment. CA date 10/12/2019 see photo #3 Location is dry, weather is clear. A follow up on this site inspection needs to be conducted to ensure that Compliance issues are addressed to comply with COGCC Rules. Continuing education COGCC Inspection Report Summary.</p> | revasr | 09/12/2019 |

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------|---|
| 699300158 | Location pics. | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4936380 |