

Inspection Photos
Location Name: MERLOT 34-13
API#: 05-071-08082
INSP. #: 695101331



Colorado Oil & Gas Conservation Commission
37.07892, -104.62168, 1985.0m, 228°
2019/09/12 10:35:35



Colorado Oil & Gas Conservation Commission
37.07906, -104.62155, 1989.0m, 325°
2019/09/12 10:35:54

PHOTO 1: WELLHEAD

PHOTO 2: WELL SIGN

Inspection Photos
Location Name: MERLOT 34-13
API#: 05-071-08082
INSP. #: 695101329



PHOTO 3: DITCH ON ROW NORTHEAST OF LOCTION IS ERODING NO BMP'S IN PLACE TO PREVENT DITCH FROM ERODING. REPAIR EROSION AND INSTALL BMP'S TO PREVENT MORE EROSION, COMPLY WITH RULE 1002.f. CA DATE 10-12-19

PHOTO 4: IMAGE OF OTHER IMPACTED AREAS ALONG ROW PERTAINING TO CA NOTED IN PHOTO 3.

Inspection Photos
Location Name: MERLOT 34-13
API#: 05-071-08082
INSP. #: 695101329



PHOTO 5: IMAGE OF OTHER IMPACTED AREAS ALONG ROW PERTAINING TO CA NOTED IN PHOTO 3.

PHOTO 6: BMP'S HAVE FAILED AND APPEARS TO HAVE BEEN INSTALL IMPROPERLY. REPAIR EROSION REPAIR THE BMP'S THAT HAVE FAILED AND INSTALL MORE BMP'S TO COMPLY WITH RULE 1002.f. CA DATE 10-12-19

Inspection Photos
Location Name: MERLOT 34-13
API#: 05-071-08082
INSP. #: 695101329



PHOTO 7: IMAGE OF OTHER IMPACTED AREAS ALONG ROW PERTAINING TO CA NOTED IN PHOTO 6.

PHOTO 8: IMAGE OF OTHER IMPACTED AREAS ALONG ROW PERTAINING TO CA NOTED IN PHOTO 6.

Inspection Photos
Location Name: MERLOT 34-13
API#: 05-071-08082
INSP. #: 695101329



PHOTO 9: IMAGE OF OTHER IMPACTED AREAS ALONG ROW PERTAINING TO CA NOTED IN PHOTO 6.

**PHOTO 10: GUY LINE ANCHOR MARKER IS DOWN.
Install proper guy line markers per Rule 1003.a**