

# Inspection Photos

API: 05-071-08887

Operator: TIMBER CREEK OPERATING LLC

Inspection Date: 9/12/2019



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-071-08887 | Date: 9/12/2019

## Inspection Photos



**Photo 1.** Stormwater is draining down the access road and not towards the culvert shown by red arrows.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-071-08887 | Date: 9/12/2019

## Inspection Photos



**Photo 2.** Facing toward the location. There is sections of panels laying on the ground which is unused equipment.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-071-08887 | Date: 9/12/2019