

FRAM OPERATING LLC – 10310

Location ID # 312681

API # 05-077-08780 Federal #12-2

Inspection Date : 9/10/2019



GoogleEarth view of location area showing access road with entrance off Lands End Rd (FS.00).Image date 6/17/2016.



GoogleEarth view of location.
Image date 6/17/2016

FRAM OPERATING LLC – 10310

Location ID # 312681

API # 05-077-08780 Federal #12-2

Inspection Date : 9/10/2019



Location overview from SW corner looking NW.



Location overview from NE corner looking SE.

FRAM OPERATING LLC – 10310

Location ID # 312681

API # 05-077-08780 Federal #12-2

Inspection Date : 9/10/2019



Location overview from NW corner looking SE.



Location overview from SE corner looking NW.

FRAM OPERATING LLC – 10310

Location ID # 312681

API # 05-077-08780 Federal #12-2

Inspection Date : 9/10/2019



**Tank battery with earth berms and fence.
Looking N.**



Weeds inside tank berms.

FRAM OPERATING LLC – 10310

Location ID # 312681

API # 05-077-08780 Federal #12-2

Inspection Date : 9/10/2019



Tank battery label and inspection opening



Leaking fitting at base of tank. Looking into inspection opening.

FRAM OPERATING LLC – 10310

Location ID # 312681

API # 05-077-08780 Federal #12-2

Inspection Date : 9/10/2019



Wellhead with Pump jack, fencing and sign.



Wellhead configuration.

Weeds. Open top 5 gal bucket with oil hanging on wellhead.

FRAM OPERATING LLC – 10310

Location ID # 312681

API # 05-077-08780 Federal #12-2

Inspection Date : 9/10/2019



**Spill response kit and
chemical injector secondary containment (unused)**



**Spill response kit and
chemical injector secondary containment (unused)**

FRAM OPERATING LLC – 10310

Location ID # 312681

API # 05-077-08780 Federal #12-2

Inspection Date : 9/10/2019



09.10.2019 10:01

Open top 5 gal bucket with oil hanging on wellhead.



09.10.2019 10:01

Unused equipment and parts around pump jack.

FRAM OPERATING LLC – 10310

Location ID # 312681

API # 05-077-08780 Federal #12-2

Inspection Date : 9/10/2019



Access Road crossing irrigation ditch. Looking SE



Culvert for irrigation ditch looking SW