

Inspection Photos

API: 05-071-07204

Operator: TIMBER CREEK OPERATING LLC

Inspection Date: 9/12/2019



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 05-071-07204 | Date: 9/12/2019

Inspection Photos



Photo 1. The culvert is full of sediment at outlet at the location. Corrective action of previous inspection not performed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07204 | Date: 9/12/2019

Inspection Photos



Photo 2. There is soil sloughing that occurred at the east side of the location. Corrective action of previous inspection not performed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07204 | Date: 9/12/2019

Inspection Photos



Photo 3. View of soil material that moved down the hill side.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07204 | Date: 9/12/2019

Inspection Photos



Photo 5. There is oily waste on the skid.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07204 | Date: 9/12/2019

Inspection Photos



Photo 5. No freeboard marker was found in the pit. Corrective action of previous inspection not performed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07204 | Date: 9/12/2019