

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/06/2019

Submitted Date:

09/09/2019

Document Number:

679705372

**FIELD INSPECTION FORM**

Loc ID 333342 Inspector Name: Moran, Rick On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10342  
Name of Operator: WOODARD\* SANDRA K  
Address: 602 OURAY AVENUE  
City: GRAND JUNCTION State: CO Zip: 81501

**Findings:**

- 9 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Heil, John		john.heil@state.co.us	
Kellerby, Shaun	970-712-1248	shaun.kellerby@state.co.us	
,	970-261-6589	zandi@bresnan.net	
Arauza, Steven		steven.arauza@state.co.us	
Pesicka, Conor	970-415-0789	conor.pesicka@state.co.us	
,	970-261-6589	3oilwells@gmail.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
229445	WELL	SI	06/01/2019	OW	103-07101	STAGNER 2	SI
229705	WELL	SI	06/01/2019	OW	103-07362	STAGNER 6	SI

**General Comment:**

[COGCC Inspection Report Summary.](#)

On 9-6-2019 at approximately 15:30, inspector Rick Moran, conducted a routine inspection at Sandra K Woodard well Stagner 2 and 6 in Rio Blanco county.

During this inspection the following compliance issues were observed:

- 1) Well head signs illegible. Letters are peeling off. Photos 3 & 6. Complete by 11-9-2019.
- 2) Stained & oily soil at multiple locations. Photos 8, 11, 12, 13. Complete by 10-9-2019.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

Note: Casing open to atmosphere on wells Stagner 2 & 6. No gas odor detected at Stagner 6 for which the casing vent opening is primarily plugged with dirt. Stagner 2 filled a 3 cubic ft bag in 7 minutes and the gas odor was detected 40 ft from the well head by the inspector. No odor detected at P&A well Stagner 3. Photos 5, 9, 15.

Wells are located 800 ft from the nearest residence and 900 ft from the White River.

This is a summary of inspection report 679705372.

**Location**

Overall Good:

<b>Signs/Marker:</b>			
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Well head signs are not fully legible. Letters are peeling off signs.		
Corrective Action:	Install sign to comply with Rule 210.b.	Date:	11/09/2019
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	911		
Corrective Action:		Date:	_____

<b>Good Housekeeping:</b>			
Type	OTHER		
Comment:	Pump jack, fencing, & wood on NW edge of location. Appears to be pump jack from well Stagner 2.		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Stained & oily soil around well head at Stagner 6. Stained dirt pile at NW edge of location. Stained next to crude oil tank.		
Corrective Action:	Properly treat or dispose of oily waste in accordance with 907.e.	Date:	10/09/2019

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Deadman # & Marked	# 2		
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS

CRUDE OIL	1	400 BBLs	STEEL AST		40.098550,-108.815940
Comment:					
Corrective Action:					Date:
<b>Paint</b>					
Condition					
Other (Content)					
Other (Capacity)					
Other (Type)					
<b>Berms</b>					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate				
Comment:					
Corrective Action:					Date:
<b>Venting:</b>					
Yes/No	YES				
Comment:	Casing open to atmosphere on wells Stagner 2 & 6. No gas odor detected at Stagner 6 for which the casing vent opening is primarily plugged with dirt. Stagner 2 filled a 3 cubic ft bag in 7 minutes and the odor was detected 40 ft from the well head by the inspector. No odor detected at P&A well Stagner 3.				
Corrective Action:					Date:
<b>Flaring:</b>					
Type					
Comment:					
Corrective Action:					Date:

**Inspected Facilities**

Facility ID: 229445 Type: WELL API Number: 103-07101 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: Pump jack removed from well head. Last recorded production May 2019.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 229705 Type: WELL API Number: 103-07362 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: Last recorded production May 2019.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402170144	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4931848">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4931848</a>
679705376	inspection photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4931843">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4931843</a>