

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

09/06/2019

Submitted Date:

09/09/2019

Document Number:

679705374

FIELD INSPECTION FORM

Loc ID 336550	Inspector Name: Moran, Rick	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____
------------------	--------------------------------	---	-------------------

Operator Information:

OGCC Operator Number: 10342

Name of Operator: WOODARD* SANDRA K

Address: 602 OURAY AVENUE

City: GRAND JUNCTION State: CO Zip: 81501

Status Summary:

☐ THIS IS A FOLLOW UP INSPECTION

☒ FOLLOW UP INSPECTION REQUIRED

☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

7 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:			
Contact Name	Phone	Email	Comment
Heil, John		john.heil@state.co.us	
,	970-261-6589	3oilwells@gmail.com	
Kellerby, Shaun	970-712-1248	shaun.kellerby@state.co.us	
,	970-261-6589	zandi@bresnan.net	
Arauza, Steven		steven.arauza@state.co.us	
Pesicka, Conor	970-415-0789	conor.pesicka@state.co.us	

Inspected Facilities:							
Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
229354	WELL	PR	04/15/2004	OW	103-07008	F V LARSON GOV B-15X	PR

General Comment:

COGCC Inspection Report Summary.

On 9-6-2019 at approximately 15:30, inspector Rick Moran, conducted a routine inspection at Sandra K Woodard well Stagner 7 in Rio Blanco county.

During this inspection the following compliance issues were observed:

- 1) Stained & oily soil at multiple locations. Photos 2, 3, 5. Complete by 10-9-2019.
- 2) Open bucket of fluid next to well head. Photo 6. Complete by 10-9-2019.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

Note: Casing open to atmosphere. A 3 cubic ft bag in 12 minutes with gas. Photos 4 & 7.

Well is 800 ft from the nearest residence and 950 ft from the White River.

This is a summary of inspection report 679705374.

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	911		
Corrective Action:		Date:	

Good Housekeeping:			
Type	OTHER		
Comment:	Open bucket of fluid next to well head. Bucket without wildlife protection & could be tipped over.		
Corrective Action:		Date:	10/09/2019
Type	OTHER		
Comment:	Stained soil around well head and flow line.		
Corrective Action:	Properly treat or dispose of oily waste in accordance with 907.e.	Date:	10/09/2019

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	

Venting:			
Yes/No	YES		
Comment:	Casing open to atmosphere. A 3 cubic ft bag in 12 minutes with gas.		
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	229354	Type:	WELL	API Number:	103-07008	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Last recorded production May 2019.								
Corrective Action:				Date:					

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [No apparent significant soil migration, erosion, or soil movement on location.](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402170145	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4931849
679705378	inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4931844