

Location			
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	Well now has a Sign Posted		
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:	Emergency Contact Info is now posted at well.		
Corrective Action:		Date:	
Good Housekeeping:			
Type	OTHER		
Comment:	Stained soil around gas engine and wellhead, See photos 3 & 4.		
Corrective Action:	Remove and/or remediate stained soil around wellhead, gas engine. Comply w/ Rule 907.e.	Date:	08/26/2019
Type	UNUSED EQUIPMENT		
Comment:	Unused Latrine still on location, See Photo 5.		
Corrective Action:	Remove unused Latrine near access road. Comply w/ Rule 603.f.	Date:	08/26/2019
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Equipment:			
Type: Deadman # & Marked	# 4	corrective date	
Comment:	All 4 Deadman Ancors need to be Marked, see photos 7 & 8		
Corrective Action:	Mark guy line anchors per Rule 604.c.(2)Q.	Date:	09/23/2019
Type: Bradenhead	# 0		
Comment:	Does not appear to be plumbed to surface		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:	Protective guard has been installed around pumpjack crank arms. See Photo 6		
Corrective Action:		Date:	
Venting:			
Yes/No			
Comment:			
Corrective Action:		Date:	
Flaring:			

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 239220 Type: WELL API Number: 123-07007 Status: PR Insp. Status: PR

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action: Date: _____

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Wednesday 09/04/2019 at approximately 13:39, I, Inspector Erica Petrie, conducted a Field Inspection at Sunburst, INC., Henderson #2, at Location #405711 in Weld County, Colorado. During this inspection the following possible compliance issues were observed: 1.) Operator name & Emergency contact number has been posted at wellsite. No further action is required at this time. 2.) Stained soil around gas engine and wellhead. Oily Waste. Refer to Rule 907.e. Remove and/or remediate stained soil around wellhead, gas engine. Comply w/ Rule 907.e. Corrective Action date: 08/26/2019. See photos 3 & 4. 3.) Remove unused Latrine near access road. Comply w/ Rule 603.f. Corrective Action date: 08/26/2019. See photo 5 4.) Weeds have been mowed and cut around wellsite, pumpjack, engine, access road. No further action is required. 5.) Protective guard around pumpjack crank arms has been installed. No further action is required. 6.) Deadman Guy Line Anchors are not marked, Mark guy line anchors per Rule 604.c.(2)Q. , Correction Action Date: 09/23/2019. A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report. Continuing Education Inspections</p>	petrie	09/06/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402170779	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4932347
696300573	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4932339