

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/13/2019

Submitted Date:

09/16/2019

Document Number:

679705444

**FIELD INSPECTION FORM**

Loc ID 315562 Inspector Name: Moran, Rick On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10112  
Name of Operator: FOUNDATION ENERGY MANAGEMENT LLC  
Address: 5057 KELLER SPRINGS RD STE 650  
City: ADDISON State: TX Zip: 75001

**Findings:**

4 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Energy, Foundation		regulatory@foundationenergy.com	Regulatory

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
231045	WELL	SI	10/01/2017	GW	103-08714	COLUMBINE SP FED 2-20-4-103	PA

**General Comment:**

[COGCC Inspection Report Summary.](#)

On 9-13-2019 at approximately 14:00, inspector Rick Moran, was on site for the P&A of Foundation Energy Management well Columbine Springs Federal 2-20-4-103 in Rio Blanco county.

No corrective actions were identified.

Note: Gas meter building and 1 deadman on location. Three pulled deadman lying on ground.

This is a summary of inspection report 6797054444.

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

Type				corrective date
Type: Gas Meter Run	# 1			
Comment:				
Corrective Action:				Date:
Type: Deadman # & Marked	# 1			
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No			
Comment:			
Corrective Action:			Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 231045 Type: WELL API Number: 103-08714 Status: SI Insp. Status: PA

**Cement**

Cement Contractor

Contractor Name: Duco Inc

Contractor Phone: 970-629-1906

Surface Casing

Cement Volume (sx): \_\_\_\_\_

Circulate to Surface: \_\_\_\_\_

Cement Fall Back: \_\_\_\_\_

Top Job, 1" Volume: \_\_\_\_\_

Intermediate Casing

Cement Volume (sxs): \_\_\_\_\_

Good Return During Job: \_\_\_\_\_

Production Casing

Cement Volume (sx): \_\_\_\_\_

Good Return During Job: \_\_\_\_\_

Plugging Operations

Depth Plugs(feet range): \_\_\_\_\_

Cement Volume (sx): \_\_\_\_\_

Good Return During Job: YES

Cement Type: \_\_\_\_\_

Comment: 2nd cement plug from previous day tragged at 1074'.  
3rd cement plug with retainer placed at 750' followed by a planned 40 sxs cement through the well head. Inspector observed the cement come to surface at 15:20.

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Completion**

Operation: \_\_\_\_\_

Date Flowback: \_\_\_\_\_

Contractor: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
679705445	inspection photo	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4937953">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4937953</a>