

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/16/2019

Submitted Date:

09/16/2019

Document Number:

692602502

FIELD INSPECTION FORM

Loc ID 303960 Inspector Name: Welsh, Brian On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10699
Name of Operator: OWN RESOURCES OPERATING LLC
Address: 38 PALMER CREST CT
City: SPRING State: TX Zip: 77381

Findings:

- 13 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

| Contact Name | Phone | Email | Comment |
|--------------|----------------|-----------------------------|---------|
| Jones, Greg | (970) 630-3909 | greg.jones@ownresources.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 253845 | WELL | PR | 01/05/1996 | GW | 125-07723 | BAGLEY 3-12 | PR |

General Comment:

[Routine Inspection](#)

| Location | | | |
|--|---|--------|-----------------|
| Lease Road: | | | |
| Type | Access | | |
| comment: | Two track through pasture | | |
| Corrective Action: | | Date: | |
| Overall Good: <input checked="" type="checkbox"/> | | | |
| Signs/Marker: | | | |
| Type | OTHER | | |
| Comment: | Lease signs for associated wells by VGS | | |
| Corrective Action: | | Date: | |
| Type | WELLHEAD | | |
| Comment: | Lease sign by unit | | |
| Corrective Action: | | Date: | |
| Emergency Contact Number: | | | |
| Comment: | | | |
| Corrective Action: | | | Date: _____ |
| Overall Good: <input checked="" type="checkbox"/> | | | |
| Spills: | | | |
| Type | Area | Volume | |
| In Containment: No | | | |
| Comment: | | | |
| <input type="checkbox"/> Multiple Spills and Releases? | | | |
| Fencing/: | | | |
| Type | LOCATION | | |
| Comment: | Wire fence around entire location | | |
| Corrective Action: | | Date: | |
| Type | PUMP JACK | | |
| Comment: | Metal panels around unit, wellhead, VGS and meter sheds | | |
| Corrective Action: | | Date: | |
| Equipment: | | | |
| Type: Ancillary equipment | # 1 | | corrective date |
| Comment: | Electric panel | | |
| Corrective Action: | | Date: | |
| Type: Deadman # & Marked | # 4 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Vertical Separator | # 4 | | |
| Comment: | 4-Vertical gas separators 50% buried by meter sheds | | |
| Corrective Action: | | Date: | |

| | | | |
|---------------------|--|-------|--|
| Type: Pump Jack | # 1 | | |
| Comment: | Jensen unit. Horsehead removed and stored neatly on location | | |
| Corrective Action: | | Date: | |
| Type: Gas Meter Run | # 4 | | |
| Comment: | Shared meter run for Bagley 3-12, 4-12, 5-12 & 8-12 | | |
| Corrective Action: | | Date: | |
| Type: Prime Mover | # 1 | | |
| Comment: | Electric motor | | |
| Corrective Action: | | Date: | |

Venting:

| | | | |
|--------------------|----|-------|--|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

Inspected Facilities

Facility ID: 253845 Type: WELL API Number: 125-07723 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing. Casing production. Downhole equipment still in wellbore. Central meter run for \(Bagely 3-12, 4-12, 5-12 & 8-12\)](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Compaction | Pass | Compaction | Pass | | | |

Comment: [Erosion leading off of location to the east needs maintenace](#)

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT