

Inspection Photos  
Location Name: Linnebur 6-13  
Location ID: 320469



Pic 1 excavation of spill site



Pic 2

**Inspection Photos**  
**Location Name: Linnebur 6-13**  
**Location ID: 320469**



**Pic 3 excavation**

**Pic 4**

**Inspection Photos**  
**Location Name: Linnebur 6-13**  
**Location ID: 320469**



COLORADO OIL AND GAS CONSERVATION COMMISSION  
39.82632, -104.15138, 4929.5ft, 217°  
09/16/2019 10:05:17

**Pic 5 flame inside ECD**



COLORADO OIL AND GAS CONSERVATION COMMISSION  
39.82632, -104.15133, 4931.1ft, 341°  
09/16/2019 10:05:45

**Pic 6 no cover on Vertical Heated Separator flange**

Inspection Photos  
Location Name: Linnebur 6-13  
Location ID: 320469



**Pic 7 Midstream equipment de-commissioned**



**Pic 8 Midstream equipment de-commissioned**

Inspection Photos  
Location Name: Linnebur 6-13  
Location ID: 320469



**Pic 9 Midstream equipment de-commissioned**



**Pic 10 Midstream equipment de-commissioned**

**Inspection Photos**  
**Location Name: Linnebur 6-13**  
**Location ID: 320469**



**Pic 11 excavation**



**Pic 12 excavation**

Inspection Photos  
Location Name: Linnebur 6-13  
Location ID: 320469



COLORADO OIL AND GAS CONSERVATION COMMISSION  
39.82634, -104.15135, 4931.2ft, 196°  
09/16/2019 10:08:21



COLORADO OIL AND GAS CONSERVATION COMMISSION  
39.82634, -104.15134, 4931.3ft, 260°  
09/16/2019 10:08:26

**Pic 13 Trash inside separator house**

**Pic 14 mechanical conditions/stained soil in separator house**

Inspection Photos  
Location Name: Linnebur 6-13  
Location ID: 320469



**Pic 15 ECD, and vertical separator.**



**Pic 16 mechanical conditions in separator house**

**Inspection Photos**  
**Location Name: Linnebur 6-13**  
**Location ID: 320469**



**Pic 17**

**Pic 18**