

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/16/2019

Submitted Date:

09/16/2019

Document Number:

699500061**FIELD INSPECTION FORM**Loc ID 320469 Inspector Name: MEDINA, JUSTIN On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 95620Name of Operator: WESTERN OPERATING COMPANYAddress: 1165 DELAWARE STREET #200City: DENVER State: CO Zip: 80204**Status Summary:**

- ☒
- THIS IS A FOLLOW UP INSPECTION
-
- ☒
- FOLLOW UP INSPECTION REQUIRED
-
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

Findings:5 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Canfield, Chris		chris.canfield@state.co.us	
Ash, Margaret		margaret.ash@state.co.us	
Gomez, Jason		jason.gomez@state.co.us	
, COGCC		conor.pesicka@state.co.us	
James, Steven	(303) 893-2438	steve@westernoperating.com	All Inspections
Chesson, Robert		robert.chesson@state.co.us	
,		dnr_cogccengineering@state.co.us	
Burn, Diana		diana.burn@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
256059	WELL	PR	10/11/2010	OW	001-09397	LINNEBUR 6-13	PR

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Bird Protectors

2

Comment:

Corrective Action:

Date:

Type: Emission Control Device

1

Comment: appears to be burning all gas coming into location

Corrective Action:

Date:

Type: Vertical Heated Separator

1

Comment:

Corrective Action:

Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	300 BBLS	STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity		Permeability (Wall)		Permeability (Base)		Maintenance			
Earth	Adequate		Walls Sufficient		Base Sufficient		Adequate			
Comment:										
Corrective Action:									Date:	
Contents		#	Capacity	Type		Tank ID	SE GPS			
CRUDE OIL		3	300 BBLS	STEEL AST			,			
Comment:										

Corrective Action:				Date:	
Paint					
Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					
Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:
Venting:					
Yes/No	NO				
Comment:					
Corrective Action:					Date:
Flaring:					
Type	Ignitor/Combustor				
Comment:	ECD Appears to be burning all gas on location, see pic 5, 7,8,9,10. Midstream equipment is de-commissioned and LOTO.				
Corrective Action:					Date:

Inspected Facilities				
Facility ID: 256059	Type: WELL	API Number: 001-09397	Status: PR	Insp. Status: PR
Producing Well				
Comment:	PR			
Corrective Action:				Date:

--

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
This is a follow up inspection for spill on location. All corrective actions from previous inspection Document # 699500031 are still valid This inspection is a follow up concerning flaring issues see pic 5,7,8,9,10,15	medinaj	09/16/2019

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699500062	pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4938770