

Location

Lease Road:			
Type	Access		
comment:	appears to be in the process of reclamation.		
Corrective ActionL		Date:	

Overall Good:

Emergency Contact Number:	
Comment:	<input style="width: 80%;" type="text"/>
Corrective Action:	<input style="width: 80%;" type="text"/>
	Date: _____

Overall Good:

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 243122 Type: WELL API Number: 123-10913 Status: TA Insp. Status: PA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: Appears to be PA and in process of reclamation.

Corrective Action: _____ Date: _____

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Monday 9/16/2019 at approximately 1000 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at the Carl R Deepe Kerr McGee, at Location # 319236 in Weld County Colorado. While there I observed a PA Wellsite. This is a follow up inspection per Doc. # 688402088. The following compliance issue has been addressed: 603.f: Unmarked, unused and not LO/TO Flow line riser. Report shows the well as TA. At the time of this inspection it appears to be PA, All WH and production equipment have been removed and access road and location appear to be in process of reclamation. See attached photos. Form 6 was submitted on 3/21/2019 Doc. # 401981119 Form 42 was submitted on 5/22/2019 Doc. # 402052456 Location is dry, weather is clear. Continuing education COGCC Inspection Report Summary. This is a summary of inspection report.</p>	revasr	09/16/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699300170	Location pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4938909