

**Inspection Photos**  
**Operator: BP America**  
**Location/API #: 067-07009**  
**Date: 9-6-2019**



Photo 1. View of northern portion of project area fencing material identified during May inspection is no longer present.



Photo 2. View of area along edge of revegetation area, where Canada thistles are treated.



Photo 3. View of the beginning of germination transect within the eastern project area. Revegetation is recently conducted. Straw mulch is crimped into the soil, and some germination observed, although sparse.



Photo 4. Birsdeye view of vegetation within germination quadrat.