

Inspection Photos

API: 05-071-06397

Operator: TIMBER CREEK OPERATING LLC

Inspection Date: 9/16/2019



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-06397 | Date: 9/16/2019

Inspection Photos



Photo 1. Facing northeast along the reclaimed access road. Perennial vegetation is well established.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-06397 | Date: 9/16/2019

Inspection Photos



Photo 2. Facing northeast along the reclaimed access road. Perennial vegetation is well established.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-06397 | Date: 9/16/2019

Inspection Photos



Photo 3. There were several noxious weeds (Bull thistle).



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-06397 | Date: 9/16/2019

Inspection Photos



Photo 4. Facing north along the reclaimed access road. Perennial vegetation is well established.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-06397 | Date: 9/16/2019

Inspection Photos



Photo 5. Facing north at the location. Perennial vegetation is uniformly established.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-06397 | Date: 9/16/2019