

# Inspection Photos

API: 05-071-06456

Operator: TIMBER CREEK OPERATING LLC

Inspection Date: 9/16/2019



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 05-071-06456 | Date: 9/16/2019

## Inspection Photos



**Photo 1.** Facing southwest along the reclaimed access road. Perennial vegetation is uniformly established. Rock rip/rap was placed in drainage area.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-071-06456 | Date: 9/16/2019



## Inspection Photos



**Photo 2.** The access road is recontoured and reclaimed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-071-06456 | Date: 9/16/2019



## Inspection Photos



**Photo 3.** Facing southwest along the reclaimed access road. Perennial vegetation is uniformly established.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-071-06456 | Date: 9/16/2019



## Inspection Photos



**Photo 4.** Facing north at the location. Perennial vegetation is uniformly established.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-071-06456 | Date: 9/16/2019



## Inspection Photos



**Photo 5.** Facing east at the location. Perennial vegetation is uniformly established.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-071-06456 | Date: 9/16/2019