

Inspection Photos
Operator: BP America
Location/API #: 067-07546
Date: 9-10-2019



Photo 1. View of the project area from the southwestern edge facing center.



Photo 2. View of the northern project area from the northeastern edge facing westward. Outer revegetation areas are infested with noxious weeds, including musk thistle, Scotch thistle, houndstongue, and Russian knapweed.



Photo 3. View of the southern project area from the southwestern edge facing eastward. Little desirable vegetation is present. Vegetation in foreground is largely annual weeds such as prostrate knotweed (*Polygonum arenastrum*).



Photo 4. Closeup view of musk thistles, houndstongues, and Scotch thistles within the outer revegetation area.



Photo 5. View of area where concentrated stormwater flows off of the southern project area. This stormwater BMP is not adequate here as bare soils throughout the revegetation area are not stabilized.



Photo 6. View of reference area east of project area, comprised of grassland field vegetation such as smooth brome and western wheatgrass.