

Inspection Photos
Location Name: Harry Ewing C #1
Location ID: 311352



Photo #1 Electric panel appears to be shut off




Photo #2 unused unmarked no LOTO flow line riser