

Location			
Lease Road:			
Type	Access		
comment:	Adequate		
Corrective ActionL			Date:
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____
Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:	Unused, unmarked no LOTO flowline riser by PU		
Corrective Action:	Comply with Rule 603.f For unused , unmarked flowline risers 24 hrs to lock out tag out. 30 days to remove riser.		Date: <u>10/17/2019</u>
Type	DEBRIS		
Comment:	Dead weeds by electric panel		
Corrective Action:	Comply with Rule 603.f 10 days for trash		Date: <u>09/27/2019</u>
Type	TRASH		
Comment:	fenceposts, barb wire, pipe.		
Corrective Action:	Comply with Rule 603.f 10 days for trash		Date: <u>09/27/2019</u>
Type	UNUSED EQUIPMENT		
Comment:	Unused Transformers and Meter box appear disconnected		
Corrective Action:	Comply with Rule 603.f 30 days for unused equipment when machinery is not required to remove the equipment. 90 days for unused equipment when machinery is required to remove the equipment.		Date: <u>10/17/2019</u>
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No _____			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	PUMP JACK		
Comment:	Fabricated angle iron		
Corrective Action:			Date:
Equipment:			
Type: Bradenhead	# 1		corrective date

Comment: Appears to be plumbed to surface			
Corrective Action:			Date:
Type: Pump Jack	# 1		
Comment:			
Corrective Action:			Date:
Type: Prime Mover	# 1		
Comment: Electric motor			
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment: Electric transformers, electric panel and meter box			
Corrective Action:			Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities

Facility ID: 245730 Type: WELL API Number: 123-13525 Status: PR Insp. Status: IO

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: appears to be inactive electric panel appears to be shut off

Corrective Action: _____ Date: _____

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Tuesday 9/17/19 at approximately 1100 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at the Harry Ewing C #1 KP Kauffman, at API #05-123-13525 in Weld County Colorado. While there, I observed an inactive wellsite. The report shows it as PR at the time of this inspection it appears inactive, the electric panel appears to be shut off see photo # 1 of location b pics.</p> <p style="text-align: right;">During this inspection the following possible compliance issues were observed: Housekeeping: Trash fence posts, barbwire, pipe and debris on location Comply with rule 603.f 10 days for Trash. CA date 9/27/2019 see photos #4,5, 6 and 7. Unused equipment: unused electric transformers and meter box. Comply with Rule 603.f 30 days for unused equipment when machinery is not required to remove the equipment. 90 days for unused equipment when machinery is required to remove the equipment. CA date 10/17/2019 see photo #3. Unused equipment: Unused, Unmarked not LOTO flow line risers around location. Comply with Rule 603.f for unused, unmarked flow line risers 24 hrs. to lock out tag out. 30 days to remove riser. CA date 10/17/2019 see photo #2 in location b pics. Location is dry, weather is cloudy. A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules. Continuing education COGCC Inspection Report Summary. This is a summary of inspection report.</p>	revasr	09/17/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699300184	Location pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4940188
699300185	Location pics b	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4940189