

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/09/2019

Submitted Date:

09/09/2019

Document Number:

679705379

**FIELD INSPECTION FORM**

Loc ID 315031	Inspector Name: Moran, Rick	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	<b>Status Summary:</b>  <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED  <b>Findings:</b>  6 Number of Comments 2 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested
<b>Operator Information:</b>  OGCC Operator Number: 10725  Name of Operator: VALKYRIE OPERATING LLC  Address: 1600 STOUT STREET SUITE 1000  City: DENVER State: CO Zip: 80202				
				<b>ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE</b>

**Contact Information:**

Contact Name	Phone	Email	Comment
Dunham, Tyson	(307)388-2290	tdunham@valkyrieoperating.com	All Inspections
Kellerby, Shaun	970-712-1248	shaun.kellerby@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
230131	WELL	PR	11/11/2005	OW	103-07790	FEDERAL 2-30	PR

**General Comment:**

[COGCC Inspection Report Summary.](#)

On 9-9-2019 at approximately 14:00, inspector Rick Moran, conducted a routine inspection at Valkyrie Resources well Federal 2-30 in Rio Blanco county.

During this inspection the following compliance issues were observed:

- 1) Stained soil on both sides of pump jack & between well head and pump jack. Photos 2, 3, 4, 5. Complete by 10-9-2019.
- 2) Missing "911" on well head sign. Photo 6. Complete by 10-9-2019.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report 679705379.

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: Missing "911" on well head sign.

Corrective Action: Install sign to comply with Rule 210.b. Date: 10/09/2019

**Good Housekeeping:**

Type	OTHER		
Comment:	<u>Stained soil on both sides of pump jack &amp; between well head and pump jack.</u>		
Corrective Action:	<u>Control and contain spills/releases and clean up per Rule 906.a.</u>	Date:	<u>10/09/2019</u>

Overall Good: ☐

<b>Spills:</b>					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities			
Facility ID: 230131	Type: WELL	API Number: 103-07790	Status: PR
		Insp. Status: PR	
Producing Well			
Comment:	Pump jack idle at time of inspection.		
Corrective Action:		Date:	

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: No apparent significant soil migration, erosion, or soil movement on location.

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402172984	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4934264">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4934264</a>
679705380	inspection photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4934255">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4934255</a>