

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/11/2019

Submitted Date:

09/11/2019

Document Number:

699300147

FIELD INSPECTION FORM

Loc ID 318334 Inspector Name: Revas, Robbie On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 46290
Name of Operator: KP KAUFFMAN COMPANY INC
Address: 1675 BROADWAY, STE 2800
City: DENVER State: CO Zip: 80202

Findings:

- 8 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

| Contact Name | Phone | Email | Comment |
|--------------|-------|-------------------------|---------------------------------|
| , | | cogcc@kpk.com | All Inspections |
| Gomez, Jason | | jason.gomez@state.co.us | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|--------------------|-------------|
| 241126 | WELL | PR | 09/03/1976 | OW | 123-08914 | MORIE GERHARDT B 6 | PR |

General Comment:

Location

| | | | |
|--------------------|----------|--|-------|
| Lease Road: | | | |
| Type | Access | | |
| comment: | Adequate | | |
| Corrective Action: | | | Date: |

Overall Good:

| | | | |
|----------------------|----------|--|-------|
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | Adequate | | |
| Corrective Action: | | | Date: |

| | | | |
|----------------------------------|--|--|-------------|
| Emergency Contact Number: | | | |
| Comment: | | | |
| Corrective Action: | | | Date: _____ |

| | | | |
|---------------------------|--|--|------------------|
| Good Housekeeping: | | | |
| Type | WEEDS | | |
| Comment: | Weeds growing around unused equipment | | |
| Corrective Action: | Comply with rule 603.f 10 days for weeds | | Date: 09/21/2019 |

Overall Good:

| | | | |
|----------------|------|--------|--|
| Spills: | | | |
| Type | Area | Volume | |

In Containment: No

Comment: _____

Multiple Spills and Releases?

| | | | |
|--------------------|----------|--|-------|
| Fencing/: | | | |
| Type | WELLHEAD | | |
| Comment: | Barbwire | | |
| Corrective Action: | | | Date: |

| | | | |
|--------------------|--|--|-----------------|
| Equipment: | | | corrective date |
| Type: Bradenhead | # 1 | | |
| Comment: | does not appear to be plumbed to surface | | |
| Corrective Action: | | | Date: |
| Type: Plunger Lift | # 1 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

| | | | |
|--------------------|----|--|-------|
| Venting: | | | |
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

| | | | |
|-----------------|--|--|--|
| Flaring: | | | |
|-----------------|--|--|--|

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

| Inspected Facilities | | |
|--|-------------------------|------------------------------|
| Facility ID: <u>241126</u> | Type: <u>WELL</u> | API Number: <u>123-08914</u> |
| Status: <u>PR</u> | Insp. Status: <u>PR</u> | |
| Producing Well | | |
| Comment: <u>PR</u> | | |
| Corrective Action: | | Date: |
| | | |
| COGCC Comments | | |
| Comment | User | Date |
| <p>COGCC Inspection Report Summary On Wednesday 9/11/19 at approximately 1600 hrs. I, Inspector Robbie Revas, Conducted an on-site Follow up inspection at the Morie Gerhardt B #6 KP Kauffman, API #05-123-008914 per Doc. #693500735 in Weld County Colorado. While there, I observed Producing Well. Well report shows it to be PR at the time of this inspection it appears to be PR.</p> <p style="padding-left: 40px;">During this inspection the following compliance issue appears to have been addressed: 210.e WH sign faded and not legible, new sign installed. See photos #1 and 2.</p> <p>CA for 603.f unused equipment onsite. Pumping unit equipment, cattle panels and electric panel has no meter is delinquent as of 8/11/2019 per Doc. # 693500735. See photos #2, 3, 4 and 5</p> <p>Housekeeping: Weeds are growing around unused equipment. Comply with Rule 603.f 10 days for weeds. CA date 9/21/2019 see photos #3, 4 and 5.</p> <p>Location is dry, weather is cloudy.</p> <p>A follow up on this site inspection needs to be conducted to ensure that the compliance issue is addressed to comply with COGCC rules.</p> <p>Continuing education COGCC Inspection Report Summary.</p> | revasr | 09/11/2019 |

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 402173828 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4935042 |
| 699300148 | Loc.pics | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4935037 |