

Inspection Photos
Location Name: Vera L Mccannon 1
Location ID: 159787



Pic 1



Pic 2

Inspection Photos
Location Name: Vera L Mccannon 1
Location ID: 159787



Pic 3 Multiple wells going to site

Pic 4 Stained soil/mechanical issues

Inspection Photos
Location Name: Vera L Mccannon 1
Location ID: 159787



Pic 5 stained soil/possible leak on bottom of tank

Pic 6 stained soil/possible leak on bottom of tank

Inspection Photos
Location Name: Vera L Mccannon 1
Location ID: 159787



Pic 7 stained soil/possible leak on bottom of tank

Pic 8 stained soil/possible leak on bottom of tank

Inspection Photos
Location Name: Vera L Mccannon 1
Location ID: 159787



Pic 9 mechanical conditions/stained soil

Pic 10 mechanical conditions/stained soil

Inspection Photos
Location Name: Vera L Mccannon 1
Location ID: 159787



Pic 11 stained soil/mechanical conditions



Pic 12 unused not LOTO riser/stained soil

Inspection Photos
Location Name: Vera L Mccannon 1
Location ID: 159787



Pic 13 storage of chemicals/no BMP/stained soil



Pic 14 storage of chemicals/no BMP/storage of unused equipment/stained soil

Inspection Photos
Location Name: Vera L Mccannon 1
Location ID: 159787



COLORADO OIL AND GAS CONSERVATION COMMISSION
40.07794, -104.88956, 4924.7ft, 253°
09/17/2019 13:05:48

Pic 17 stained soil/mechanical conditions



COLORADO OIL AND GAS CONSERVATION COMMISSION
40.07794, -104.88955, 4930.0ft, 270°
09/17/2019 13:05:56

Pic 18 mechanical conditions in separator house