

Inspection Photos
Location Name: UPRR 42 Pan Am AF #2
Location ID: 318387



Photo #1 WH sign faded



Photo #2 PU

Inspection Photos
Location Name: UPRR 42 Pan Am AF #2
Location ID: 318387



Photo #3 Weeds growing around Electric transformer.



Photo #4 Stained soil under flow line

Inspection Photos
Location Name: UPRR 42 Pan Am AF #2
Location ID: 318387




Photo #5 Stained soil around WH

Photo #6 PU appears to have leaking gasket