

KP Kauffman - COGCC Inspection Photos
Location: Thomas L. Russell B #1 Flowline Spill
Spill ID #467496



Wellhead, Pump Jack and Signage



View from Thomas L. Russell B 1 well (API 123-07574) east to the spill/ release point and excavation.

KP Kauffman - COGCC Inspection Photos
Location: Thomas L. Russell B #1 Flowline Spill
Spill ID #467496



View of the excavation and 4" Carbon Steel crude oil consolidation flowline exposed in excavation. Impacts to ground water can be seen. (view to North)



Close up view of flowline at the point of failure (coating is hanging down). A clamp was observed where a historical repair was completed.

KP Kauffman - COGCC Inspection Photos
Location: Thomas L. Russell B #1 Flowline Spill
Spill ID #467496



View to North from the excavation at point of release to the excavation completed approximately 150' to the North.



View from the excavation completed to expose the crude oil consolidation line for the repair to the south excavation where the spill occurred.