

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/18/2019

Submitted Date:

09/18/2019

Document Number:

696500640

FIELD INSPECTION FORM

Loc ID 445473 Inspector Name: Peterson, Tom On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10311

Name of Operator: SRC ENERGY INC

Address: 1675 BROADWAY SUITE 2600

City: DENVER State: CO Zip: 80202

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

18 Number of Comments

6 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		cogccinspections@srcenergy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
445672	WELL	PR	07/01/2017	OW	123-43167	SRC WILLIAMS 12-4-5NM-C	PR
445673	WELL	SI	05/01/2019	OW	123-43168	SRC WILLIAMS 11-4-5NM-C	SI
445674	WELL	SI	06/01/2019	OW	123-43169	SRC WILLIAMS 12-4-5NM-A	SI
445675	WELL	PR	06/01/2017	OW	123-43170	SRC WILLIAMS 12-4-5CM	PR
445676	WELL	SI	06/01/2019	OW	123-43171	SRC WILLIAMS A-4-5NM-A	SI
445677	WELL	SI	01/01/2019	OW	123-43172	SRC WILLIAMS 11-4-5NM-A	SI
445678	WELL	PR	07/01/2017	OW	123-43173	SRC WILLIAMS A-4-5NM-C	PR
445679	WELL	PR	04/01/2018	OW	123-43174	SRC WILLIAMS 11-4-5CM	PR
445680	WELL	PR	07/01/2017	OW	123-43175	SRC WILLIAMS 22-4-5NM-C	PR

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	CONTAINERS		
Comment:	Unplacarded chemical container next to separators. See attached photo.		
Corrective Action:	Install sign to comply with Rule 210.d.	Date:	10/21/2019
Type	WELLHEAD		
Comment:	x 9		
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Two concrete vaults on north side of location, one fiberglass vault next to control house and one concrete vault next to compressor are not placarded. See attached photos.		
Corrective Action:	Install sign to comply with Rule 210.d.	Date:	10/21/2019

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	Electric transformer trench on south side of location has subsided and electric lines appear to be exposed. See attached photo.		
Corrective Action:	Comply with Rule 605.c.	Date:	10/21/2019
Type	UNUSED EQUIPMENT		
Comment:	Unused flange bolts next to north side of tank berm. See attached photo.		
Corrective Action:	Comply with Rule 603.f .	Date:	10/21/2019
Type	TRASH		
Comment:	Trash on south side of separators. See attached photo.		
Corrective Action:	Comply with Rule 603.f .	Date:	10/21/2019

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	OTHER		
Comment:	Temporary flag tape around transformer		

Corrective Action:			Date:		
Equipment:			corrective date		
Type: LACT	# 1				
Comment:					
Corrective Action:			Date:		
Type: Pig Station	# 1				
Comment:					
Corrective Action:			Date:		
Type: Horizontal Heated Separator	# 9				
Comment:					
Corrective Action:			Date:		
Type: Compressor	# 2				
Comment:					
Corrective Action:			Date:		
Type: Emission Control Device	# 5				
Comment: Pilots are on					
Corrective Action:			Date:		
Type: Bradenhead	# 9				
Comment: Bradenhead valves are exposed at surface.					
Corrective Action:			Date:		
Type: Plunger Lift	# 9				
Comment:					
Corrective Action:			Date:		
Type: Vertical Separator	# 4				
Comment:					
Corrective Action:			Date:		
Type: Gas Meter Run	# 2				
Comment:					
Corrective Action:			Date:		
Type: Ancillary equipment	#				
Comment: Automation array, electrical equipment, control houses, bulk oil tanks and chemical barrels in containment with bird netting, ECD scrubbers, chemical systems					
Corrective Action:			Date:		
Type: Bird Protectors	# 14				
Comment:					
Corrective Action:			Date:		

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	400 BBLS	STEEL AST		,
Comment:					

Corrective Action:		Date:	
--------------------	--	-------	--

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
	4	OTHER	BV CONCRETE		,
Comment:	Unknown contents and capacity				
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Other	Inadequate	Walls Insufficient	Base Sufficient	Inadequate
Comment:	Concrete vaults on north side of tank battery and at compressor have no berms, fiberglass vault at control house has no berm. See attached photos.			
Corrective Action:	Repair or install berms or other secondary containment devices per Rule 605.a.(4).			Date: 10/21/2019

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	8	400 BBLs	STEEL AST		40.360200,-104.882860
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Inspected Facilities

Facility ID: 445672 Type: WELL API Number: 123-43167 Status: PR Insp. Status: PR

Producing WellComment: PR

Corrective Action:

Date:

Facility ID: 445673 Type: WELL API Number: 123-43168 Status: SI Insp. Status: SI

Idle WellPurpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: _____

Corrective Action: _____

Date: _____

Facility ID: 445674 Type: WELL API Number: 123-43169 Status: SI Insp. Status: SI

Idle WellPurpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: _____

Corrective Action: _____

Date: _____

Facility ID: 445675 Type: WELL API Number: 123-43170 Status: PR Insp. Status: PR

Producing WellComment: PR

Corrective Action:

Date:

Facility ID: 445676 Type: WELL API Number: 123-43171 Status: SI Insp. Status: SI

Idle WellPurpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: _____

Corrective Action: _____

Date: _____

Facility ID: 445677 Type: WELL API Number: 123-43172 Status: SI Insp. Status: SI

Idle WellPurpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: _____

Corrective Action: _____

Date: _____

Facility ID: 445678 Type: WELL API Number: 123-43173 Status: PR Insp. Status: PR

Producing WellComment: PR

Corrective Action:

Date:

Facility ID:	445679	Type:	WELL	API Number:	123-43174	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:								Date:	

Facility ID:	445680	Type:	WELL	API Number:	123-43175	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:								Date:	

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Friday 9/6/2019 at approximately 14:15 hours, I, Inspector Tom Peterson, conducted an on-site inspection at the SRC Energy SRC Williams Pad location #445473 in Weld County Colorado.</p> <p>While there, I observed three concrete vaults and one fiberglass vault with no placards, three concrete vaults and one fiberglass vault with insufficient berms, an electric transformer with an open trench and exposed power lines, trash and unused equipment. During this inspection the following possible compliance issues were observed: Rule 210.d. with a corrective action date of 10/21/19, Rule 603.f. with a corrective action date of 10/21/2019, Rule 605.c. with a corrective action date of 10/21/19.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of the inspection report.</p>	petersont	09/18/2019

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696500641	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4941177