

Inspection Photos
Operator Name: Caerus Piceance LLC
Location ID: 334069



Flowline repaired and is in service.

Carbon to poly

Inspection Photos
Operator Name: Caerus Piceance LLC
Location ID: 334069



New Flowline installed

Inspection Photos
Operator Name: Caerus Piceance LLC
Location ID: 334069



New Flowline Installed