

Inspection Photos
Operator: BP America
Location/API #: 067-07002
Date: 9-10-2019



Photo 1. View of the project area from the southeastern edge facing center.



Photo 2. View of the southern fill slope from the southeastern edge facing westward. Revegetation is progressing with smooth brome and western wheatgrass.



Photo 3. View of erosion and sediment run-on in the northeastern project area. Soils on northeastern cut-slopes are largely bare and need revegetation.



Photo 4. View of reference area vegetation facing westward. Vegetation is comprised of mixed pinyon juniper, squaw apple, and sagebrush shrubland.