

Inspection Photos
Operator: Hilcorp Energy
Location/API #: 067-08231
Date: 9-10-2019



Photo 1. View of the project area from the southwestern edge facing center.



Photo 2. View of the western fill slope from the southwestern edge facing northward. Revegetation is progressing largely with western wheatgrass and smooth brome.



Photo 3. View of flowering musk thistles within the interim reclamation area.



Photo 4. View of reference area vegetation facing southward. Vegetation is comprised of sagebrush shrubland.