

Location			
Lease Road:			
Type	Access		
comment:	Adequate		
Corrective Action			Date:
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	<input style="width: 100%;" type="text"/>		
Corrective Action:	<input style="width: 100%;" type="text"/>		Date: _____
Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:	Unused Electric panel. Shares location with KP Kauffman well		
Corrective Action:	Comply with Rule 603.f		Date: 10/19/2019
Overall Good: <input checked="" type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:	<input style="width: 100%;" type="text"/>		
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	WELLHEAD		
Comment:	AG fence		
Corrective Action:			Date:
Type	PUMP JACK		
Comment:	Fabricated angle iron		
Corrective Action:			Date:
Equipment:			
Type: Pump Jack	# 1		corrective date
Comment:			
Corrective Action:			Date:
Type: Prime Mover	# 1		
Comment:	Gas powered engine		
Corrective Action:			Date:
Type: Plunger Lift	# 1		
Comment:			

Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 2		
Comment:	Kerr McGee Appears to be plumbed to surface, KP Kauffman does not appear plumbed to surface		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Automation		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 284712 Type: WELL API Number: 123-23867 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action: Date: _____

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Thursday 9/19/19 at approximately 1330 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at the Debeque V #27-2 Kerr McGee, at API #05-123-23867 in Weld County Colorado. While there, I observed SI wellsite. Shared location with KP Kauffman well. During this inspection the following compliance issues were observed: Housekeeping: unused equipment (electric panel). Comply with rule 603.f, 30 days for unused equipment when machinery is not required to remove the equipment. CA date 10/19/2019. See photo #3 Location is dry, weather is clear. A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules. Continuing education COGCC Inspection Report Summary. This is a summary of inspection report.</p>	revasr	09/19/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699300228	Location pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4942270