

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/19/2019

Submitted Date:

09/19/2019

Document Number:

699300220**FIELD INSPECTION FORM**

Loc ID 332883 Inspector Name: Revas, Robbie On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:11 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Gomez, Jason		jason.gomez@state.co.us	
,		COGCCinspections@anadarko.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
256988	WELL	SI	09/01/2018	GW	123-19949	HSR-ALLEN 12-26A	SI

General Comment:

Location

Lease Road:			
Type	Access		
comment:	Adequate		
Corrective Action	L	Date:	

Overall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:			
Corrective Action:			
	Date:		

Overall Good: ☒

Spills:					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	OTHER		
Comment:	Electric panel transformers anf meter box Fabricated pipe		
Corrective Action:		Date:	
Type	PUMP JACK		
Comment:	Fabricated angle iron		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	AG fence		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Ancillary equipment	# 2		
Comment:	Electric panel transformers and meter box. Automation		
Corrective Action:		Date:	
Type: Bradenhead	# 2		
Comment:	Appears to be plumbed to surface		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	

Type: Prime Mover	# 1		
Comment:	Electric motor		
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 256988 Type: WELL API Number: 123-19949 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: SI

Corrective Action: _____

Date: _____

COGCC Comments

Comment

User

Date

COGCC Inspection Report Summary
 On Thursday 9/19/19 at approximately 1200 hrs. I, Inspector Robbie Revas,
 Conducted an on-site inspection at the HRS-Allen #12-26A Kerr McGee, at
 API #05-123-19949 in Weld County Colorado.
 While there, I observed SI Well site. Form 42 submitted on 7/17/2017 Doc. # 401343614.
 Shared location with KP Kauffman well.
 During this inspection no compliance issues were observed:
 Location is dry, weather is clear.
 Continuing education COGCC Inspection Report Summary.
 This is a summary of inspection report.

revasr

09/19/2019

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699300221	Location pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4942267