

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/19/2019

Submitted Date:

09/19/2019

Document Number:

679705515

FIELD INSPECTION FORM

Loc ID 398836	Inspector Name: Moran, Rick	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input checked="" type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED Findings: 15 Number of Comments 0 Number of Corrective Actions <input type="checkbox"/> Corrective Action Response Requested
Operator Information: OGCC Operator Number: 100264 Name of Operator: XTO ENERGY INC Address: 110 W 7TH STREET City: FORTH WORTH State: TX Zip: 76102				ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Reid, Van		van_reid@xtoenergy.com	
Dooling, Jessica	970-769-6048	Jessica_Dooling@xtoenergy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
301740	WELL	PR	07/17/2009	GW	103-11465	PICEANCE CREEK UNIT 297-11C5	PR
301741	WELL	PR	05/29/2012	GW	103-11466	PICEANCE CREEK UNIT 297-11C4	PR
301742	WELL	PR	08/01/2017	GW	103-11467	Piceance Creek Unit 297-11C8	SI
301743	WELL	PR	07/01/2018	GW	103-11468	PICEANCE CREEK UNIT 297-11C1	SI
301744	WELL	PR	09/08/2010	GW	103-11469	Piceance Creek Unit 297-11C7	PR
301745	WELL	PR	09/18/2010	GW	103-11470	PICEANCE CREEK UNIT 297-11C2	PR
301746	WELL	PR	07/17/2009	GW	103-11471	Piceance Creek Unit 297-11C9	PR
301747	WELL	PR	07/17/2009	GW	103-11472	PICEANCE CREEK UNIT 297-11C6	PR
301748	WELL	PR	07/17/2009	GW	103-11473	PICEANCE CREEK UNIT 297-11C3	PR

General Comment:

COGCC Inspection Report Summary.

On 9-19-2019 at approximately 16:00, inspector Rick Moran, conducted a routine well inspection at XTO Energy wells Piceance Creek Unit 297 in Rio Blanco county.

No corrective actions were identified.

This is a summary of inspection report 679705515.

LocationOverall Good: ☒

Signs/Marker:			
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911

Corrective Action:

Date: _____

Overall Good: ☒

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	LOCATION		
Comment:			
Corrective Action:		Date:	

Equipment:			corrective date
Type: Deadman # & Marked	# 10		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 9		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Separator	# 1		
Comment:	In building.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 2		

Comment:	Containers of SCI-8760 with secondary containment.			
Corrective Action:			Date:	
Type: Other		# 1		
Comment:	RTU building			
Corrective Action:			Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities									
Facility ID:	301740	Type:	WELL	API Number:	103-11465	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well on plunger lift.								
Corrective Action:						Date:			
Facility ID:	301741	Type:	WELL	API Number:	103-11466	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well on plunger lift.								
Corrective Action:						Date:			
Facility ID:	301742	Type:	WELL	API Number:	103-11467	Status:	PR	Insp. Status:	SI
Idle Well									
Purpose:	<input checked="" type="checkbox"/> Shut In		<input type="checkbox"/> Temporarily Abandoned		Reminder:				
Comment:	Last recorded production June 2019.								
Corrective Action:						Date:			
Facility ID:	301743	Type:	WELL	API Number:	103-11468	Status:	PR	Insp. Status:	SI
Idle Well									
Purpose:	<input checked="" type="checkbox"/> Shut In		<input type="checkbox"/> Temporarily Abandoned		Reminder:				
Comment:	Last recorded production June 2019.								
Corrective Action:						Date:			
Facility ID:	301744	Type:	WELL	API Number:	103-11469	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well on plunger lift.								
Corrective Action:						Date:			
Facility ID:	301745	Type:	WELL	API Number:	103-11470	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well on plunger lift.								
Corrective Action:						Date:			
Facility ID:	301746	Type:	WELL	API Number:	103-11471	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well on plunger lift.								
Corrective Action:						Date:			
Facility ID:	301747	Type:	WELL	API Number:	103-11472	Status:	PR	Insp. Status:	PR

<u>Producing Well</u>			
Comment:	Producing well on plunger lift.		
Corrective Action:		Date:	
Facility ID: 301748 Type: WELL API Number: 103-11473 Status: PR Insp. Status: PR			
<u>Producing Well</u>			
Comment:	Producing well on plunger lift.		
Corrective Action:		Date:	

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			
Gravel	Pass	Gravel	Pass	Material Handling And Spill Prevention	Pass	

Comment: No apparent significant soil migration, erosion, or soil movement on location.

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
679705516	inspection photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4942364