

FORM  
INSPRev  
X/15

## State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/19/2019

Submitted Date:

09/20/2019

Document Number:

679705519

### FIELD INSPECTION FORM

Loc ID 335711 Inspector Name: Moran, Rick On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 100264Name of Operator: XTO ENERGY INCAddress: 110 W 7TH STREETCity: FORTH WORTH State: TX Zip: 76102**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Findings:**11 Number of Comments0 Number of Corrective Actions Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Dooling, Jessica	970-769-6048	Jessica_Dooling@xtoenergy.com	
Reid, Van		van_reid@xtoenergy.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
278098	WELL	PR	03/01/2017	GW	103-10589	PICEANCE CREEK UNIT T62X-11G2	PR
278099	WELL	PR	03/01/2019	GW	103-10588	PICEANCE CREEK UNIT T62X-11G1	PR
278134	WELL	PA	02/15/2006	GW	103-10592	PICEANCE CREEK UNIT T62X-11G4	PA
278135	WELL	PR	03/01/2019	GW	103-10591	PICEANCE CREEK UNIT T62X-11G3	PR
278161	WELL	PA	10/19/2007	GW	103-10593	PICEANCE CREEK UNIT T62X 11G5	PA

**General Comment:**

[COGCC Inspection Report Summary.](#)

On 9-19-2019 at approximately 16:30, inspector Rick Moran, conducted a routine well inspection at XTO Energy wells Piceance Creek Unit T62X-11G in Rio Blanco county.

No corrective actions were identified.

This is a summary of inspection report 679705519.

**Location**

Overall Good:

<b>Signs/Marker:</b>			
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	OTHER		
Comment:	Chemical.		
Corrective Action:		Date:	
Type	LOCATION		
Comment:			
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Horizontal Separator	# 1		
Comment:	In building with secondary containment.		
Corrective Action:		Date:	
Type: Plunger Lift	# 2		
Comment:			
Corrective Action:		Date:	
Type: Other	# 2		

Comment: <a href="#">Storage building and headers.</a>		Date:
Corrective Action:		Date:
Type: Ancillary equipment	# 2	
Comment: <a href="#">One container of methanol with secondary containment and 1 container of SCI-8760 both with secondary containment.</a>		Date:
Corrective Action:		Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	400 BBLs	STEEL AST		39.897270,-108.245630
Comment:					
Corrective Action:		Date:			

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient		Adequate
Comment:				
Corrective Action:		Date:		

**Venting:**

Yes/No	NO
Comment:	
Corrective Action:	
Date:	

**Flaring:**

Type	
Comment:	
Corrective Action:	
Date:	

**Inspected Facilities**

Facility ID: 278098 Type: WELL API Number: 103-10589 Status: PR Insp. Status: PR

**Producing Well**

Comment: Producing well.

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

Facility ID: 278099 Type: WELL API Number: 103-10588 Status: PR Insp. Status: PR

**Producing Well**

Comment: Producing well.

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

Facility ID: 278134 Type: WELL API Number: 103-10592 Status: PA Insp. Status: PA

**Idle Well**

Purpose:  Shut In       Temporarily Abandoned      Reminder: \_\_\_\_\_

Comment: Well P&A Februrary 2006. No suface evidence of well.

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

Facility ID: 278135 Type: WELL API Number: 103-10591 Status: PR Insp. Status: PR

**Producing Well**

Comment: Producing well.

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

Facility ID: 278161 Type: WELL API Number: 103-10593 Status: PA Insp. Status: PA

**Idle Well**

Purpose:  Shut In       Temporarily Abandoned      Reminder: \_\_\_\_\_

Comment: Well P&A October 2007. No suface evidence of well.

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass					
Berms	Pass			Material Handling And Spill Prevention	Pass	
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
679705520	inspection photo	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4942548">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4942548</a>