

Inspection Photos

API: 05-071-07989

Operator: TIMBER CREEK OPERATING LLC

Inspection Date: 9/19/2019



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07989 | Date: 9/19/2019

Inspection Photos



Photo 1. Facing toward the wellhead. There was signs that the well was recently leaking.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07989 | Date: 9/19/2019

Inspection Photos



Photo 2. Water level at pit is at 2ft freeboard and needs to be lowered.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07989 | Date: 9/19/2019

Inspection Photos



Photo 3. Facing east at the interim reclamation area. There were noxious weeds (Scotch thistle) found around the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07989 | Date: 9/19/2019