

Inspection Photos

API: 05-071-06411

Operator: TIMBER CREEK OPERATING LLC

Inspection Date: 9/19/2019



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-06411 | Date: 9/19/2019

Inspection Photos



Photo 1. Facing east toward the location. West of the well site. Perennial vegetation is well established in this area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-06411 | Date: 9/19/2019

Inspection Photos



Photo 2. Facing west toward the location. West of the well site. Perennial vegetation is well established in this area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-06411 | Date: 9/19/2019

Inspection Photos




Photo 3. There are some noxious weeds that have grown at the eastern side of location. Common mullien.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-06411 | Date: 9/19/2019

Inspection Photos



Photo 4. There is a metal pipe that remains at the east side of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-06411 | Date: 9/19/2019