

Inspection Photos

API: 05-071-06436

Operator: TIMBER CREEK OPERATING LLC

Inspection Date: 9/19/2019



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-06436 | Date: 9/19/2019

Inspection Photos




Photo 1. Facing west toward the reclaimed access road from the bottom of the canyon. There are numerous noxious weeds in this area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-06436 | Date: 9/19/2019

Inspection Photos



Photo 2. There are Scotch thistle rosette that need to be controlled.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-06436 | Date: 9/19/2019

Inspection Photos



Photo 3. Facing east toward the reclaimed access road from the bottom of the canyon.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-06436 | Date: 9/19/2019

Inspection Photos



Photo 4. Facing northeast along the reclaimed access road. Vegetation is establishing well.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-06436 | Date: 9/19/2019

Inspection Photos



Photo 5. There are noxious weeds along the road which have developed seed heads.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-06436 | Date: 9/19/2019

Inspection Photos



Photo 6. Facing northeast along the reclaimed access road. Vegetation is establishing well. There is a dominance of Yellow clover in this area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-06436 | Date: 9/19/2019