

# Inspection Photos

Operator: Hilcorp Energy  
Location/API #: 067-09742  
Date: 9-16-2019



Photo 1. View of the project area from the northwestern corner facing center.



Photo 2. View of the western fill slope facing southward. Little vegetation present here. Revegetation is needed.





Photo 2. View of the southern project area from the southwestern corner facing eastward.





Photo 5. View of reference area vegetation, comprised of open grass field.