


TEP ROCKY MOUNTAIN LLC

SG 34-28FracPad

Location # 334397



TEP ROCKY MOUNTAIN LLC
SG 34-28FracPad
Location # 334397



Storm water channel in check dam behind tank battery.



Storm water channel in check dam behind tank battery.

TEP ROCKY MOUNTAIN LLC
SG 34-28FracPad
Location # 334397



Storm water channel in check dam behind tank battery.



Storm water channel in check dam behind tank battery.

TEP ROCKY MOUNTAIN LLC
SG 34-28FracPad
Location # 334397



Check dam across from wells has wash damage

Check dam across from wells has wash damage

TEP ROCKY MOUNTAIN LLC
SG 34-28FracPad
Location # 334397



TEP ROCKY MOUNTAIN LLC
SG 34-28FracPad
Location # 334397



Cut slope behind separators is unstable and sediment build up at base of cut.



Cut slope behind separators is unstable and sediment build up at base of cut.