

Inspection Photos
Operator: Hilcorp Energy
Location/API #: 067-09361
Date: 9-16-2019



Photo 1. View of the project area from the western corner facing center.



Photo 2. View of the western project area from the western corner facing northeastward. This portion of the well pad needs to be reclaimed.



Photo 3. View of the southern project area from the western corner facing southeastward. Truck parked on well pad shows that portions of the southern project area are not needed for production operations and need reclamation.



Photo 4. View of hose debris in the western project area.



Photo 5. View of reference area vegetation, comprised of open grass field and wetland vegetation.